

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland

(County)

Located In: Farmington Twp. Corner Code #

1. Public Land Survey

T 1-N R 9-E

E-12

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

SURVEY &
REMONUMENTATION

MAR 21 2000

SECTION

4. Lot No. , Recorded Plat

5. Private Claims

I, John N. Redash, in a field survey on March 6, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1817 Set post	S. Carpenter	n/a	G.L.O. Notes
1989 Set iron with cap	R. Donnelly	#21563	L.C.R.C. L11062 p.238

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A found capped iron #21563 N 10° W., 1.98' from a 1/2" pipe currently occupies this corner. The following witness ties were used to recover and verify its position:

4 current measurements match ties from L.C.R.C. L11062 p. 238. Field measurements were made between the following corner

E-11 to E-12	E-12 to E-13
2654.95 meas.	2640.61 meas.
2640.00 Rec. G.L.O.	2641.00 G.L.O.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the found 1/2" iron with a 4" x 36" concrete monument with a 2" diameter brass cap stamped "Oakland County Remonumentation PS 37281." Witnesses are as follows:

N 75° W.,	114.96'	N.E. Building corner
S 80° W.,	116.94'	S.E. Building corner
N 30° E.,	19.97'	P.K. nail and remon. washer W. face 30" Oak
S 20° W.,	9.53'	P.K. nail and remon. washer W. face 24" Oak

The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by John N. RedashDate April 24, 1997Surveyor's Michigan License No. 37281

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 11
REVISED MAY 14, 18
REVISED JAN., 11
REVISED OCT., 11

\$ 7.00 MISCELLANEOUS RECORDING
\$ 2.00 REMONUMENTATION H I J K L
2 JAN 98 9:03 A.M. RECEIPT 12A
PAID 6 RECORDED - OAKLAND COUNTY
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

4	7	8	9	10	11	12
5						
6	18	17	16	15	14	13
7						
8	19	20	21	22	23	24
9						
10	30	29	28	27	26	25
11						
12	31	32	33	34	35	36
13						

