

LIBER 18345 PC 394

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland
(County)

Located in: Corner Code #
West Bloomfield Township

1. Public Land Survey

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

T2N R9E M-3
T R
T R
T R
S T R
S T R
S T R
S T R

\$ 7.00 MISCELLANEOUS RECORDING
\$ 2.00 REMONUMENTATION
15 APR 98 1:23 P.M. RECEIPT# 225A
PAID RECORDED - OAKLAND COUNTY
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 4-7-18 JS
OAKLAND COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

SECTION

I, Huston K. Kennedy, in a field survey on February 20, 1998 o hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:
1817-GLO Carpenter, D.S.; Set Post 21" Aspen N32°E 45 Links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1998-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a 1/2" Iron Rod w/2" diameter brass cap stamped Oakland County Remonumentation, PS #24598 in a existing Monument Box located in the existing centerline of Square Lake Road extending to the East & West, which has a bituminous surface.

FIELD MEASUREMENTS BETWEEN

M-3 to A-3
Common Corner

M-3 to M-4

GLO = 40 chains or 2640.00 Ft.
"UPPER LONG WOODS" + LONG RIDGE" (Sec 12) = 2629.89 Ft.
2629.89 Ft. (GPS-MEA)

M-3 to M-2

GLO = 40 chains or 2640.00 Ft.
"HAMMOND LAKE ESTATES NO. 1" (Sec 1) = 2650.10 Ft. & 2649.28 Ft. (GPS-MEA)
2649.28 Ft. (GPS-MEA)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
M-3 I accept the found 1/2" Iron Rod w/2" diameter brass cap stamped Oakland County Remonumentation, PS #24598 in a existing Monument Box
N12°W 62.01' Set PK & Remon Washer SW face Power Pole
Due North 43.80' Set PK & Remon Washer East face 28" Oak
S51°E 48.69' Set PK & Remon Washer NE face 11" Poplar
S45°W 59.16' Set PK & Remon Washer NW face 10" Box Elder

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by:

Surveyor's Michigan License No. 17623

Date

4-10-98



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995