LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 3 N. R. 9 E.	<i>A</i> -3	
2. PROPERTY CONTROLL- 7 ING IN SECTION —	,т. 3 ,, R. 9 Е.	A-3	
3. MISCELLANEOUS PROPERTY IN SECTION			
4. LOT NO, RECO	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on July 1923, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey or July 19 1923, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Recovered I'' Iron Ripe with Brass Cap Set by R.L.S. Lee Paddison IN 1957			
C. Description of monument for I'' I RON Pipe U N. 34° W 10.70' N. 08° E 11.77' S 82° W 26.40'	uith BrassCap - 18" B.Oak -14" B.Oak	established to perpetuate loc	ating the position of the corner:
S 36°W - 8.25°	1 - 8" HICKORY	(ved Mul in Face	
SURVEYOR'S MICHIGAN REG		<i>29</i>	(SEAL)
FOR STATE AND UNITED STA		DATE	
			LOTAL)
	MICHIGAN REGISTERED I	CAMP SURVETOR	(SEAL)