

LIBER 20101PC711

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

OAKLAND

(County)

Located In: PONTIAC Corner Code # E-3

## 1. Public Land Survey

T 3NR 10E E-3T RT RT RT RT RT RT RT R2. Property Controlling  
in SectionST RST R3. Miscellaneous  
Property in Sec.ST RST RST R

SECTION

## 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

## 5. Private Claims \_\_\_\_\_

RAYMOND J. McCOYMar. 27 99

I, RAYMOND J. McCOY, in a field survey on Mar. 27 99, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

WAMPLER, D.S., SET POST.THERE ARE NO L.C.R.C.'S RECORDED.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found capped rod #16042. There are no distinctive physical features leading away from the corner. Corner was recovered from a survey drawing of the City of Pontiac Landfill and various field notes from different time periods. Corner fits very closely with the City of Pontiac records for this corner (Field Notes & Drawings).

State Plane Coordinates N 436209.4206  
E 13412380.7718

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced the found capped iron with a concrete monument, consisting of a 1/2" iron rod encased in a 4" diameter concrete cylinder 36" long with a 2" diameter brass disk stamped Oakland County Remonumentation P.S. #21270.

## WITNESSES:

N 45° E, 147.59' Set cross cut on S. Rim of San. M.H.S 80° E, 312.95' Set cross cut on W. Rim of C.B.S 45° W, 128.93' Set cross cut on N. Rim of C.B.S 80° W, 493.11' Set cross cut on E. Rim of C.B.

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER

Signed by Raymond J. McCoy  
Surveyor's Michigan License No. 21270

Date June 4, 1999

206151

LIBER 20101 PAGE 711

\$7.00 MISC RECORDING

\$2.00 REMONUMENTATION

06/10/1999 12:32:43 P.M. RECEIPT

PAID RECORDED - OAKLAND COUNTY

G. WILLIAM CADDELL, CLERK/REGISTRAR

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 4-4-99 JS  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE

Register of Deeds Stamp &amp; File Number

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												