

SURVEY & REMONUMENTATION

LIBER 15235 PG 078

FEB 29 02 02 94

OK - T. SMITH

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE \$ 7.00 MISCELLANEOUS RECORDING
Filing Requirement of Act 74, Mich. P.A. 1970 \$ 2.00 REMONUMENTATION

For corners in

Oakland
(County)

COMMISSION

Located In:

Corner Code #

- | | | |
|-------------------------|-----------|-----|
| 1. Public Land Survey | T 4N R 9E | G-6 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling | S T R | |
| in Section | S T R | |
| 3. Miscellaneous | S T R | |
| Property in Sec. | S T R | |

2 FEB 95 9:41 A.M. RECEIPT# 508
PAID RECORDED - OAKLAND COUNTY
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 1-25-95
OAKLAND COUNTY REMONUMENTATION
PEER GROUP COMMITTEE
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, James J. Scharl, in a field survey on December 19, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Post set in
1817 G.L.O. survey

LCRC - L 8960, P 450
1-18-85, 3/8" iron pin found
Willis F. Titsworth

N 20°E 26 Lks 12" W. Oak
S 42°W 16 Lks 14" W. Oak

*North 16.36' nail 8" Hickory
N 30°W 10.15' nail 12" Oak
*S 15°W 26.20' nail 18" Twin Cherry

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/8" rerod located in a tree row running north and south.

Witnesses Found

*N 15°E 16.36' nail NE face 10" Hickory
*S 10°W 26.19' nail W. face twin 18" Cherry

*Confirms LCRC witness

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set conc mon with Oakland County remonumentation brass cap, replacing the 3/8" rod.

N 15°E 16.41' set PK/remon. tag E. face 10" Hickory
N 30°W 24.50' set PK/remon. tag N. face 6" Oak
S 10°W 26.29' set PK/remon. tag W. face twin 18" Cherry
S 08°E 15.51' set PK/remon. tag S. face 4" Oak

The selected location is accepted by the Contractor and is generally accepted by
professional surveyors as the best available evidence of the position of the original
corner. This corner was also accepted by the Oakland County Peer Group as established
under Act 345 of P.A. 1990.

Signed by James J. Scharl James J. Scharl Date Dec. 28, 1994

Surveyor's Michigan License No. 19843

