## SURVEY & REMONUMENTATION

JAN 2095011242

unc 1521 % 075

	Hotels, Religious Pe	2 OK - T. 5MIH
MAN 1 1005 LAND CORNER RECORDATION CERTIFICATE		
93-1010	Filing Requirement of Act 74, Mich. P.	A. 1970 9.00 MISCELLANEOUS RECURDING
For corners in	COMMISSION	\$ 2.00 RENONUMENTATION
Oakland	Located In: Oakland Corner Code ##	20 JAN 95 7:48 A.M. RECEIPT# 11B
(County)		PAID RECORDED - OAKLAND COUNTY
Public Land Sur	rvey T <u>4N R 11E G-5</u>	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
1. 1 doile Land Out	T R	
	T R	Compliance with
	T R	ACT 345, P.A. 1990
2. Property Control		APPROVED ON: 13-19-94
in Section	S T R	OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE
3. Miscellaneous	S T R	Register of Deeds Stamp & File Number
Property in Sec.	. STR	riogister of Deeds Stamp & File Runiber
4. Lot No, Recorded Plat A.B.C.D.E.E.G.H.L.K.L.A.		
5 Private Claims	, Necoded Flat	ABCDEFGHIJKL
J. Trivate Olamis _		2 6 5 5 4 3 2 3 1 2
•		3
		4 7 8 1 1 1 1 1 1 1 1 1
I Grant J. Ward, RIS, in a field survey on November 28 19 94 5		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned		
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the		
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5		and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a		
Court of Law; established, re-established, monumented, re-monumented, recovered, found as		d as
expressed below:		10 30 29 28 27 26 25
A NATION AND AND AND AND AND AND AND AND AND AN		11 + + + + + + + + + + + + + + + + + +
on this cert	инсате.	12 - 31 - 32 - 33 - 34 - 35 - 36-
		13

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Description of original monument and accessories and/or subsequent restoration:

Post, per G.L.O. Notes.

G-5 Corner common to Sec. 9, 10, 15 & 16, T. 4 N., R. 11 E. Set Monument Box, 5/8" Iron Rod and Brass Cap #22445 0.5' South of the Centerline of Stoney Creek Road. This corner location is a careful and faithful perpetuation of the position of the original corner.

Previously Recorded in L. 5892, P. 261 (0); and L. 12838, P. 433 (0) of Oakland County Records.

- (n)Indicates the number of references that confirms this corner by dimensional tie.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner STATE UT WICHIGH Corner common to Sec. 9, 10, 15 & 16, T. 4 N., R. 11 E. Set Monument G-5 Box, 5/8" Iron Rod and Brass Cap #22445. **Due North** 18.081 Set P.K. Nail & Brass Disc #22445 in top of Guard Rail GRANT J. Post. WARD **Due South** 17.33' Set P.K. Nail & Brass Disc #22445 in top of Guard Rail LAND SURVEYOR Post. S. 50° W. NO. Set P.K. Nail & Brass Disc #22445 in top of Guard Rail Post. N. 50° W. Set P.K. Nail & Brass Disc #22445 in top of Guard Rail 36.59' Post. N. 73° E. 5.32' Found Iron Rod. \$. 03° E. 32.381 Found Iron Rod. December 27, 1994 Signed by 01° E. 33.00' Found Iron Rod.

Surveyor's Michigan License No. 22445

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28,

G-5