
## CUMMISSION



## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

AU.	1 343, P.A. 199	U
VED ON: _	12-7-95	T.5
	NTY REMONL	

		r o 19 <b>90</b>	1 1871	2 <b>15</b> 913rc759			
	<b>C</b> U11.	MISSION		RECORDATION CERTI	Compliance with		
Fo	r corners in		Filing Requirement of Act 74, Mich. P.A. 1970  APPROVED ON: 12-7-95 T-S  OAKLAND COUNTY REMONUMENTATION				
_	Oakland (County)	Located in:	Addison Township	Corner Code #	PEER GROUP COMMITTEE CC \$ 7.00 HISCELLANEOUS RECORDING		
1.	Public Land Survey	Т F	3	E-1	\$ 2.00 REHONUMENTATION 29 DEC 93 9:03 A.M. RECEIPT# 44A PAID RECORDED - OAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS		
2.	Property Controlling in Section Miscellaneous	S T F	3 3		Register of Deeds Stamp & File Number		
•	Property in Sec.	· · · · · · · · · · · · · · · · · · ·	3				
4. 5.		, Recorded Plat			A B C D F G H I J K L M		

in a field survey on 19 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

G.L.O. Set Post E-1 1817 Wampler 1872 S. Cooley Survey N/A Baldwin Iron 1930 Survey Cert. Survey L. 14100 P. 279 Corner in Lake 1992 Heil

- Description of corner evidence found and/or method applied in restoring or reestablishing corner: В.
- This corner falls in Brooks Lake survey drawing per S. Cooley 1872 shows this corner to be 2869.68' West of E-1 N 1/4 corner Section 4 (F-1). Survey prepared by Baldwin shows same measurement to N 1/4 Section 4 (F-1) and also shows E-1 to be 536.06' West of the E-13 Lapeer County.

Found an old 3/4" iron at both the N 1/4 corner of Section 4 and E-13 Lapeer County.

Measure between corners = 2322.64 Baldwin Survey Measures = 2333.62

Decided to hold Baldwin distance of F36.06' West of E-13 Lapeer County to establish E-1. Used line of iron West of E-13, to establish section line. Total distance measurement from this point to G-1 is 5724.84'. Record distance per Cooley 1872 and Baldwin 1930 is 5739.36' or 14.52' longer than our measured distance. Found a 3/4" iron on East bank of Brooks Lake 48.55' East of computed location of E-1. This point is on town line as established.

Because the best evidence on record for this corner is the Baldwin measurement to E-13 Lapeer County, I recommend that this corner be established holding said measurement as defined above and reference monument be set.

Date

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F-1 Replaced the 1/2" rebar with a 4" x 36" concrete monument with brass cap stamped "Oakland County Remonumentation P.S. #25854."

PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in W Face 5" Cedar N 52° E 67.00' PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in NW Face 24" Red Pine N 70° E 22.13' PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in N Face 12" Oak S 84° E 37.84' PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in W Face 12" Cedar S 17° E 21.87' E. Edge Lake West 6.00'

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Signed by EARTH TECH 25854

Surveyor's Michigan License No.

10

11