

STATE OF MICHIGAN  
COUNTY OF OCEANA  
RECEIVED FOR RECORD

3 DEC 1999 2:13:06 PM

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oceana  
(County)

Located in:

Corner Code #

1. Public Land Survey

T15N R18W

J-7

2. Property Controlling  
in Section

S

T

R

3. Miscellaneous  
Property in Sec.

S

T

R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

JOSEPH E. MERTEN  
REGISTER OF DEEDS

100945

Register of Deeds Stamp & File Number

I, J. Randolph Hepworth, in a field survey on October 14, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

|    | A | B  | C | D  | E | F  | G | H  | I | J  | K | L  | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 2  |   | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |
| 3  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 4  |   | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |
| 5  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 6  |   | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |
| 7  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 8  |   | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |
| 9  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 10 |   | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |
| 11 |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 12 |   | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |
| 13 |   |    |   |    |   |    |   |    |   |    |   |    |   |

A. Description of original monument and accessories and/or subsequent restoration:

J-7 1/4 CORNER COMMON TO SECTIONS 14 AND 23 T15N, R18W GOLDEN TOWNSHIP

GLO J. Mullett 1838 SET POST 10" Beech N30°E (31 lks) 20.5' 10" Beech S44°W (14 lks) 9.2'

Book A, Pg. 298, S Edson, 1891; No witnesses cited.

Unrecorded Survey, JR Hepworth # 26457, 5/12/93 Fd 1/2" Iron, NWSE, RLS 16923

- 1) 12" W Pine 21°az 28.10'
- 2) 10" R Pine 82°az 13.22'
- 3) 6" S Pine 175°az 24.20'
- 4) 24" Pine Stump W 6'
- 5) 6" Maple Clp 125°az 64.66'

Oceana County Remonumentation  
Peer Group Reviewed & Approved

Date: 11-11-99

J. Randolph Hepworth  
Oceana County Surveyor

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

I found a NWES (Northwest Eng. & Surveying) 1/2" Iron & Cap, RLS16923, inside a steel U-post in concrete at the intersection of old occupation lines N-S & E-W. This corner was re-established by S. Barnett using single proportion between I-7 and K-7. As this Iron fits local occupation and since I have no other historical description of this corner, I accepted it as found.

I accept the Iron as a careful and faithful re-establishment of the position of the original corner. No evidence is known to me that would lead me to believe the corner should be at another location.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 4"x20" Harrison Cast Iron Monument, stamped "County Surveyor" and "26457" above the 1/2" Iron which was driven down.

|            |        |               |        |        |     |
|------------|--------|---------------|--------|--------|-----|
| 3) 60d spk | W Face | 10" R Pine    | 175°az | 24.07' | EDM |
| 5) 60d spk | N Face | 10" clp Maple | 125°az | 64.53' | EDM |
| 60d spk    | S Face | 4" Cherry     | 270°az | 68.61' | EDM |
| 60d spk    | S Face | 3" Maple      | 63°az  | 13.41' | EDM |



Signed by

*J. Randolph Hepworth*

Surveyor's Michigan License No. 26457

Date November 30, 1999