

# SURVEY & REMONUMENTATION

OCT 27 1993

COMMISSION

## OCEANA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
COUNTY OF OCEANA  
RECEIVED FOR RECORD

100505

'93 OCT -7 P2:45

For corners in

OCEANA  
(County)

Located in:

Corner Code #

1. Public Land Survey	T	15N	R	17W	G-7
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S		T	R	
	S		T	R	
3. Miscellaneous Property in Sec.	S		T	R	
	S		T	R	

*Joseph E. Martin*  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2			
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

J. Randolph Hepworth in a field survey on September 27, 1993

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A. G-7 CORNER COMMON TO SEC 15, 16, 21 & 22 HART TWP T15N, R17W  
GLO SET POST 10" BEECH S16°E 27.7' 12" BEECH N35°E 19.8'  
BOOK A - 130 S. EDSON JAN, 1982 CORNER NOT DESCRIBED OR WITNESSED  
OCRC WITNESS BOOK: 4-10-51 PD 1" IRON  
10" MAPLE N12°W 29.0' COR FENCE POST S45°E 47.4'  
20" ELM N70°E 67.4' P POLE S45°E 110.8'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

FOUND 1/2" IRON BY HEPWORTH, PS AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

G-7 CORNER COMMON TO SEC 15, 16, 21 & 22 HART TWP T15N, R17W  
SET "COUNTY SURVEYOR" HARRISON 4"x20" CAST IRON MONUMENT IN PLACE OF FOUND 1/2" IRON  
CENTERLINE INTERSECTION OF E-W PAVEMENT AND N-S GRAVEL ROADS

60d SPK	NW FACE	POWER POLE	S55°W	60.20	TAPE
60d SPK	SW FACE	GUY POLE	N50°W	59.35	TAPE
CENTER		STOP SIGN	N20°W	43.14	TAPE
CENTER		STOP SIGN	S25°E	44.30	TAPE
CENTER		STREET SIGN	N40°E	41.9	TAPE
CENTER		5" ELM	N85°E	165.10	TAPE



Signed by *J. Randolph Hepworth*

Date September 30, 1993

Surveyor's Michigan License No. 26457