

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
OGEMAW
(County)

Located In

Corner Code #

1. Public Land Survey	T	22N	R	3E	E-3
	T	22N	R	3E	F-3
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

Register of Deeds Stamp & File Number

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on March 8, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-3 – Section corner common to sections 4,5,8&9, T22N,R03E

F-3 – ¼ corner common to Sections 4&9, T22N,R03E

1846 – GLO – B.F. Hall Tamarack 16 inches for corner to sections 4,5,8&9

1846 – GLO – B.F. Hall set quarter section post
W. Pine 22 S49 E 09 lks
Hemlock 20 S16W 10 lks

1960 – James E. Richardson RLS #2527 set corner by single proportionate measurement between the ¼ corner to the South and Township line to the North.

1960 – James E. Richardson RLS #2527 found a post of recent origin with two other post bottoms in close proximity.

Wits: J. Pine 5" S32°W 32.21
Maple 8" N49 1/2°W 37.58
Balsam 8" N61°E 22.35

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

E-3 – Section corner common to sections 4,5,8&9, T22N,R03E

F-3 – ¼ corner common to Sections 4&9, T22N,R03E

Found ½" x 12" pipe fitting Richardson's survey in sections 4,5,8&9. Found no other evidence to dispute the location for the corner.

Found ¾" x 1 ¼" rod in a good East – West fence fitting Richardson's survey and witnesses in section 4. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3 – Section corner common to sections 4,5,8&9, T22N,R03E

F-3 – ¼ corner common to Sections 4&9, T22N,R03E

Drove 1"x36" pipe with Standard DNR cap over found 1" pipe

¾" x 1 ¼" rod

Wit: N16°E 30.48' to fd Nail E side 14" Maple Clump
S25°E 12.25' to fd Nail W side 8" Cedar
S49°W 26.42' to fd Nail W side 12" Cedar
N65°W 19.06 to fd Nail NE side 10" Cedar
N44°W 59' to Fence Corner wire going E-W & S

Wit: N51°E 23.67' to set N&T SE side 9" R. Maple
S30°W 33.92' to fd nail NW side 15" Dead J. Pine
S35°W 0.68' to set PK N&T RR Tie F. Post
N50°W 37.23' to fd Nail SW side 22" R. Maple
N03°W 19.60' to set N&T E side 9" Oak

Signed by:

Carl T. Kiiskila

Date:

8-15-12

Surveyor's Michigan License No.:

33981

