## LAND CORNER RECORDATION CERTIFICATE

	Filing Requirement of	Act 74, Mich. PA 1970
For Corners In: Ogemaw (County)	Located In Corner C	ode#
1. Public Land Survey	T 24N R 2E D-11 T 24N R 2E C-11	
Property Controlling in Section	STR	
3. Miscellaneous Property in Section	S T R S T R	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	ABCDEFGHIJKLM
5. Private Claims:		2 - 6 - 5 - 4 - 3 - 2 - 1
requirements of PA 74, Mic and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	survey on October 24, 2005 do hereby state the chigan PA of 1970, the corner points mentioned is mance with regulations and rules therefore as revery instructions of the United States Department or by a decree of a Court of Law and/ollines 3, 4 and 5 above were in conformance with a Land Surveyors or by a Decree of a Court monumented, recovered, found as expressed belong the property of the conformance of the	in lines 1 quired in nt of the r that the the rules of Law; ow:
NOTE: Not more than be recorded on this ce	2 corners, all in the same town and range rtificate.	, may  10  11  12  31  32  33  34  35  36  13
D-11 G.L.O. J.H. Mulli Wit: Spruce Pine Spruce Pine 1936 Marcus Schaaf I	6" N06°W 18 links R.L.S. #3104 set a 1 ½" pipe in	ent restoration: C-11 G.L.O. J.H. Mullet 1846 set post to sections 29,30,31 and 32. Wit: Spruce Pine 6" S31°W 16 links Spruce Pine 6" N49°W 15 links 1936 Marcus Schaaf R.L.S. #3104 set a 1 ½" pipe in
concrete midway and No witnesses given.	online between section corners.	concrete for corner. No witnesses given
	CARL KIISKILA LAND SURVEYOR	George Henning R.L.S. #2240 1956 map shows a ½" X 24 iron for corner  Wit: 8" Norway N60°W 53.6'  10" B. Oak S53°W 56.1'  8" J. Pine S51°E 75.7'
<b>3</b>	SURVEYOR No. 33981	Liber 2, Page 40, 1989 Timothy L. Lapham R.L.S. #27595 found a ½" iron for corner.
`\	LAND SURVEY	Wit:10" J. Pine S80°W 54.03' P. Pole N35°W 45.55' 8" Oak S40°E 62.51' Ctr road intersection N,S, and E
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:		
D-11 Found 1 ½" pipe	as set by Marcus Schaaf	C-11 Found 3/8" iron rod fitting T. Lapham witnesses and G. Henning's survey in section 31. Raised with 5/8" X 18" rerod with P.S. cap #33981
C. Description of monun	nent for corner and accessories established t	o perpetuate locating the position of the corner:
Wit: 8" Oak 10" Oak 3" R. Pine 4" J. Pine	#33981 to found 1 ½" pipe N39°W 50.71' N04°E 38.59' S53°W 47.84' S18°E 27.58' centerline East / West Road	C-11 5/8" X 18" rerod with P.S. cap #33981 Wit: P. Pole N37°W 45.63' 11" J. Pine S83°W 53.83' 7" J. Pine N39°E 62.55' 6" J. Pine N53°W 60.58' Centerline of N-S Road West 4'± Centerline of East to Road 5' South of centerline Road to West.
Signed by:	and T Kiskila	Date: 11/9/05
Surveyor's Michigan	License No.: 33981	