

SURVEY & REMONUMENTATION

MAR 02 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

GOGEBIC - ONTONAGON Located in:

Corner Code #

JUDITH D. ROEHM

1P

Ontonagon County

Page 1 of 1

LC 5/359

JEM Date 12/21/2000

Time 15:13:37

RECORDING FEE:

9.00

1. Public Land Survey

T46N R40W

A - 13

T46N R41W

M - 13

T45N R40W

A - 1

T45N R41W

M - 1

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Gogebic

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Township Corner, Sec's. 1, 6, 31 & 36, T45 - 46N, R40 - 41W.
2000

I, Earl W. Applekamp, in a field survey on April 28, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by William Burt, U.S. Deputy Surveyor, July 9, 1847.

ORIGINAL BEARING TREES: 15" Cedar, S50°E, 15 Links; 12" Cedar, N44°W, 10 Links.

In 1935 Corner was restored by Surveyors, Barlock & Humphrey. They set a 2"x2"x30"

Cedar Post at the record bearing and distance from the two original bearing trees.

They established one new bearing tree, a 14" Cedar, N10°E, 18 Links (11.88') on

October 14, 1965. Donald Lappala, RLS No. 12585, found the 2"x2"x30" Cedar Post,

the remains of the 14" Cedar bearing tree set by Barlock & Humphrey and remains of

the two original bearing trees established in 1847. He set a 2"x5' long concrete

filled galvanized iron pipe capped with a 3" circular bronze tablet which reads:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

T45-46N, R40-41W, S1, S6, S31, S32, RLS 12585, 1965. He established three bearing

trees: 2" Yellow Birch, N48°W, 15.8 Feet, 5" Black Spruce, S12°E, 26.6 Feet,

6" Cedar, S25°W, 18.2 Feet. I found the monument and all the bearing trees in good

condition. Corner is recorded in Gogebic County Book 1, Page A - 1.

Research on file with the Ontonagon County Remonumentation Program Representative.

DEED GROUP APPROVED
Earl W. Applekamp
COUNTY RE-ESTABLISHED 12-19-00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I added one new bearing tree:

Nail in 15" Cedar S57°E 27.68 Feet

6' Steel Sign Post, bears North 0.70 Feet from monument.

I re-painted all three bearing trees established in 1965.



Signed by Earl W. Applekamp

Date December 9, 2000

Surveyor's Michigan License No. 17610