

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON
(County)

Located in:

Corner Code #

1. Public Land Survey

T48N R41W

H-3

T R

T R

T R

2. Property Controlling in Section

S

T R

S

T R

3. Miscellaneous Property in Sec.

S

T R

S

T R

SURVEY & REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

 $\frac{1}{4}$ Corner common to Sections 3 & 10, T48N R41W.

2000

I, Earl W. Applekamp, in a field survey on June 03, 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4			3		2		1	
3													
4	7		8		9			10		11		12	
5													
6	18		17		16			15		14		13	
7													
8	19		20		21			22		23		24	
9													
10	30		29		28			27		26		25	
11													
12	31		32		33			34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner established by Wells Burt, U.S. Deputy Surveyor, June 17, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

20" Cedar N30°E 19 Links (12.54 Feet)
18" Cedar S35°W 15 Links (9.90 Feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original or subsequent evidence was found. Corner was re-established by single proportionate measure and on line between opposite Section Corners East & West.

Research on file with the Ontonagon County Remonumentation Program Representative.

Earl W. Applekamp 6-21-00
COUNTY REGISTRAR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 $\frac{1}{2}$ "x30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R41W, S3, S10, 2000, P.S. 17610. I established three bearing trees and a reference object.

Nail in 10" Maple S25°W 10.09' - Nail in Twin 4" Maple S66°E 29.95'
Nail in 10" Maple N10°W 18.86' - 6' Steel Sign Post, North 0.63'



Signed by

Earl W. Applekamp

Date June 14, 2000

Surveyor's Michigan License No. _____

17610