

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

JUDITH D. ROEHN

1P

Ontonagon County

LC 5/313

Page 1 of 1

JEM Date 07/10/2000 Time 12:13:36

RECORDING FEE:

9.00

For corners in

Ontonagon County

Located in:

Corner Code #

1. Public Land Survey

T52N R38W C-13  
T51N R38W C-1

2. Property Controlling in Section

S

T R  
T R  
T R  
T R

3. Miscellaneous Property in Sec.

S

4. Lot No.

, Recorded Plat

5. Private Claims

SURVEY & REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Joseph C. Domitrovich, in a field survey on June 2, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C-13) Corner of Sections 31 & 32, T52N, R38W & Sections 5 & 6 T51N, R38W

1845 - William A. Burt set a post with ties:

14" Sugar N 85°E 50 links  
12" Hemlock N 30°W 38 links

I Found no Record of Subsequent Restoration.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of original corner or accessories. I re-established corner position at the intersection of centerline of Kujala Road to the North and on the extension of a very old but straight fence line to the East. Another old fence wanders westerly and southerly from this position. This position works very well with other section corners to the west. I placed a county monument at this position.

Research on file with County Remonumentation Representative.

STATE BOARD APPROVED  
Earl W. Applekamp  
COUNTY REMONUMENTATION 6-21-00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" x 24" iron pin with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T52N, T51N, R38W; S. 31, S. 32, S. 5, S. 6; 2000; P.S. 37273. I also placed a reference monument, (R.M.) to the East, a 2 1/4" aluminum pipe with a 3" diameter aluminum cap stamped to indicate that the Section Corner is N 89°51'W 41.29'. Ties to the corner:

R.M. S 89°51'30"E 41.29'  
Power Pole N 67°E 38.31'  
6" Apple Tree N 66°W 25.10'  
12" Elm S 14°W 49.71'

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

Signed by

*J. C. Domitrovich*

Date

6/21/00

Surveyor's Michigan License No. 37273