Ontonagon County LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P. A 1970 of 1 EM Vate 09/06/2000

RECORDING FEE:

LC 5/338 Time 09:50:17 9.00

For comers in

Ontonagon County	Located in:		Comer Code #	
Public Land Survey		T51N T T T	R38W R R R	C-7
Property Controlling in Section Miscellaneous Property in Sec.	\$ \$ \$ \$	T T T T	R R R	

SURVEY & REMONUMENTATION

MAR 0 2 2001

SECTION


Register of Deeds Stamp & File Number

, Recorded Plat 4 Lot No.

**Private Claims** 

1, Joseph C. Domitrovich, in a field survey on August 22, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

## (C - 7) Corner Common to Sections 17, 18, 19 & 20, T51N, R38W

1846 - S. W. Higgins set a post with ties:

30" Hemlock

S 50°E

25 links

12" Sugar

N 30°W

20 links undated - William A. Nolton, R.L.S. 960, set a cedar post from the "unmistakable evidence of old Gov't Hem. Bearing

Tree. Also found mound where sugar had been blown down." He marked a 14" Hemlock, N 34°E, 38 links and a 16" Maple, S 05°E, 33 links.

1931 – Milton R. Eva, R.L.S. 1767, found Nolton's corner and the stumps of both of his bearing trees. He set a 1 ¼" pipe 1' above ground and a cedar post at this corner. (This and Nolton information from Milton Eva Field notes

at Ontonagon County Historical Museum.) 1966 - C.C. Lindgren, R.L.S. 14098, for Michigan State Highway Department, found a 1 1/2" iron pipe at a fence

intersection and gave distances to corners west and south. Ties:

S 25°W 3" Triple Maple 42.57 5" Elm N 65°W 20.91 S 85°E 47.77 14" Elm

COURTE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

OSEPH DOMITROVICH

CAND

I found no remains of the original corner of accessories. I found the bent remains of a 2" outside diameter (1 1/4" or 1 1/2" inside diameter) iron pipe. The pipe matches Lindgren's distance west to the S 1/4 Corner Section 18, but all of his B.T.'s have been taken out by Farming Activity. I believe this is the same iron pipe as set by Milton Eva at the site of the original corner. I have accepted it as the true Section Corner and have Monumented it as such. Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 36" x %" aluminum rod with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T51N, R38W; S. 17, S. 18, S. 19, S. 20; 2000; P.S. 37273. Corner falls 1.8' East and 1.0'

North of a fence intersection. Ties:

i iron pipe	2 00.44	2.00 (pipe is newer and 5 above ground	,
Steel Sign Rail	N 80°W	2.31' (to face)	Å
5" Hard Maple	N 89°W	2.31 (to face) 21.84' 18.81'	į.
10" Basswood	N 72°W	18.81'	1
6" Hard Maple	N 30°W	33.30'	
S ¼ Cor Sec 18	S 86°19'38"W	2646.71'(2646.71' Lindgren) (2640' GLO)	

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.

Signed by 💆

Surveyor's Michigan License No. 37273