JUDITH D. ROEHM

RECORDING FEE:

SURVEY &

REMONUMENTATION

MAR 02 2001

SECTION

5

7

8

10

11 12

LAND CORNER RECORDATION CERTIFICATE of 1 Ontonason County Filing Requirement of Act 74, Mich. P.Ajr 1970 te 06/12/2000

LC 5/292 Time 16:32:11 9.00

For corners in

Ontonagon County

Located In:

Comer Code #

M - 6

A - 6

1. Public Land Survey

T52N R39W T52N R38W R T R T R

2. Property Controlling in Section Miscellaneous

S Property in Sec. S

S T R T R R

, Recorded Plat

5. Private Claims

4 Lot No

I, Joseph C. Domitrovich, in a field survey on May 22, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M - 6) ½ Corner Common to Sections 13, T52N, R39W & Section 18, T52N, R38W.

1845 - William A. Burt set a Fir post with ties:

12" Sugar

N 58°E

24 links

26" Hemlock

S 35°W

7 links

I found no record of subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of original corner or accessories. At the corner position is East - West gravel Aho Road and a fence fine running North. I established a position for the 1/2 corner in centerline of the road on the extension of the fence to the North. This position works well with section corner to North and with other corners on the Range line to the South. It also works well with 1/16 fence to the West. I accepted this position as the ½ corner.

Research on file with County Remonumentation Representative.

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer:

Corner is a 5/8" x 24" iron pin with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T52N, R39W; R38W; 1/4; S. 13, S. 18; 2000; P.S. 37273. I also established a reference monument (R.M.) to the North, a 2 1/2" x 30" aluminum pipe with a 3" diameter cap stamped to indicate that the 14 corner is \$ 00°27'W, 31,372 the corner: 07 W/EN

6" Soft Maple S 60°E 44.31' 14" Ash S 44°W 38.08' Power Pole N 73°W 98.70 R.M. N 00°27'00"E 31 37 NE Cor. Sec. 13 N 00°23'27'E 2648 931

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

PEER GAOUP APPROVED

Surveyor's Michigan License No. 37273

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1973 REVISED JAN

JOSEPH

(AND

OMITROVICH

LAND JRVEYOR

Register of Deeds Stamp & File Number