

# SURVEY & REMONUMENTATION

AUG 29 1995

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Osceola  
(County)

Located In:

Corner Code #

18N 8W

M-12

- |                                    |   |   |   |
|------------------------------------|---|---|---|
| 1. Public Land Survey              | T | R |   |
|                                    | T | R |   |
|                                    | T | R |   |
|                                    | T | R |   |
| 2. Property Controlling in Section | S | T | R |
|                                    | S | T | R |
| 3. Miscellaneous                   | S | T | R |
| Property in Sec.                   | S | T | R |

APPROVED LAND CORNER  
P.A. 345 OF 1990  
Osceola County

*Matthew McClung*  
August 3, 1995

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Matthew McClung

July 20, 95

I, \_\_\_\_\_, in a field survey on \_\_\_\_\_, 19 \_\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

**A. Description of original monument and accessories and/or subsequent restoration:**

The original corner was set by deputy surveyor John Hodgson on Dec. 9, 1937. Set wood post 40.00 chains from the South. Maple 8" for Qr. Section Post.

From 1891 to 1904 approximately, Osceola County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" glazed tile filled with cinders from a forge, were placed at each government set corner in the township. There were supposed to be 3 tile per corner, placed atop of each other, (continued on back)

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

Found Osceola County Monument 2" below surface. Removed monument and excavated to 22" and found tile also found 4" wood stake at surface. 3" long 1/2" Rod at dept of tile. Placed Osceola County over Center of Tile 6" below surface.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

Corner M-12. Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 18" in length.

- 14" Walnut N16W 112.75 feet. O.B.T.
- 10" Elm N48E 41.25 feet O.B.T.
- 10" Elm N70E 66.90 feet.
- Power Pole S12W 120.92 feet.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



Signed by

*Matthew McClung*

Date July 20, 1995

Surveyor's Michigan License No.

13037

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

OSCEOLA COUNTY  
REGISTER OF DEEDS

95 AUG -9 PM12:13

*Nancy Crawford*

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records.

I have shown 3 132 PA survey certificates. Two by Wetherell and one by Knapp.