

JAN 17 1996

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

Osceola  
(County)

Located In:

Corner Code ##

18N 10W C-3

- |                                    |   |   |   |
|------------------------------------|---|---|---|
| 1. Public Land Survey              | T | R |   |
|                                    | T | R |   |
|                                    | T | R |   |
|                                    | T | R |   |
| 2. Property Controlling in Section | S | T | R |
|                                    | S | T | R |
| 3. Miscellaneous Property in Sec.  | S | T | R |
|                                    | S | T | R |

APPROVED LAND CORNER  
P.A. 345 OF 1990  
Osceola County

19 OCT 1995  
Matthew McClung

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

Matthew McClung October 14, 1995

I, \_\_\_\_\_, in a field survey on \_\_\_\_\_, 19\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 80.00 chains from South.  
Sugar 8" N68E 30 lks.  
Sugar 9" S47W 25 lks.

County Survey Records Lincoln Township Book, front pages, page 5 middle of page, pages 14 and 15, also pages 16 & 17.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found shank of ten penny spike in center line East and West Road and 10 feet West of center line of roads North and South. Found One Quarter Corner and One Sixteenth Corner to South and lined over intersection. I set the corner on this line the distance of 152.96 feet from the Northwest corner of the school (S50 1/2E 231.75 lks). Corner is 2.9 feet South of Center Line and makes the first Quarter Mile to the South short by 6.28 feet. See Sketch.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner C-3. Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 18" in length.  
Power Pole S40W 153.25 feet.  
Power Pole N50W 101.0 feet.  
NW Corner of School house S53E 152.96 feet. O.B.T.  
2" Red Pine N42E 84.0 feet.  
2" Red Pine S22E 87.8 feet.



OSCEOLA COUNTY  
REGISTER OF DEEDS  
95 NOV 13 PM 4:53

Signed by Matthew McClung Date October 14, 1995  
Surveyor's Michigan License No. 13037