

SURVEY &
REMONUMENTATION

SEP 10 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Osceola
(County)

Located In:

Corner Code #

1. Public Land Survey T 18 N R 10 W D-5
 T R
 T R
 T R
2. Property Controlling S T R
 in Section S T R
3. Miscellaneous S T R
 Property in Sec. S T R

APPROVED LAND CORNER
P.A. 345 OF 1990
Osceola County

28 May 1998
Matthew McClung

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Matthew McClung in a field survey on 6 23, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

The original corner was set by deputy surveyor John Hodgson June 10, 1938.
Set Post 39.84 chains. from East.
Birch 12" S30E 23 lks.
Birch 7" S43W 23 lks
Act 74 Liber 1, Page 339
Found Sq Hd. Bolt
N45W 47.20' 5" poplar
Due North 30.98' 4" Maple (in clump)
S40E 33.20' 6" Maple

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Excavated to 5" below surface and found Osceola County Moument. Excavated to 8" and found Sq. Head Bolt. under cap of Osceola County Monument. Removed Osceola County Monument and bolt and heard no other evicence of corner. Put Osceola County Monument and bolt back in found position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner D-5. Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 18" in length.
15" Maple S40E 32.9 feet.
S. most Maple in Clump North 30.65 feet. O.B.T.
Telephone Ped. South 26.75 feet.
MailBox Post N70W 44.9 feet.

Signed by Matthew McClung
Surveyor's Michigan License No. 13037

Date June 23, 1998

23 July 1998



OSCEOLA COUNTY
REGISTER OF DEEDS

98 JUL 23 PM 12:39

Nancy Crawford

SURVEY &
REMONUMENTATION

SEP 10 1998

SECTION

Act 74 Liber 1. Page 62

Fd. 3/4" Sq iron bar

Nail and cap in the N.E. side of a 6" Maple S38E 33.33'

Nail and Cap in the South side of a 8" Poplar N66E 48.09'

Nail and Cap in the SW side of a 4" Poplar N17W 20.54'

Act 132 Liber 306 Page 567

Fd. Sq Hd Bolt

N45W 47.20' 5" Poplar

Due N. 30.98' 4" Maple (Clump)

S40E 33.20 4" Maple