

SURVEY &
REMONUMENTATION

APR 25 1995

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

Osceola
(County)

Located In:

Corner Code #

1. Public Land Survey T 18N R 10W K-6
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

APPROVED LAND CORNER
P.A. 345 OF 1990
Osceola County

Matthew McClung
29 Nov. 1994

Register of Deeds Stamp & File Number

~~Matthew McClung~~, in a field survey on November 28, 1994,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

The original corner was set by deputy surveyor John Hodgson on 10 June
1838. Set wood post 40.00 chains from South.

Tamarack 7" S21W 6 lks.

Tamarack 9" N24E 27 lks.

There are 2 LCRC recordings, Lib. 1, page 381 by McClung and Lib 3, Page
84, by Wetherell.

There are 4 Act 132 recordings.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rod and cap No. 24624, beside 5/8" rod I set in 1975 survey.
Corner is in road cut, I estimate to be 5 feet deep, so no old corner
evidence could be found. Removed both rods and set Osceola County Monument
6" below road surface, at position of irons.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner K-6, Osceola County Monument, which is a 3" brass cap mounted on a
1" pipe 18" in length.

Telephone riser N30W 40.0 feet. O.B.P.

6" W. Pine N50E 42.67 feet. O.B.T.

10" fence post S86W 27.87 feet. O.B.P.

8" Poplar S65W 26.76 feet. O.B.T.

Nancy Crawford
94 DEC - 7 PM 2:51
OSCEOLA COUNTY
REGISTER OF DEEDS

Signed by *Matthew McClung* Date November 28, 1994
Surveyor's Michigan License No. 13037

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983