

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF --: | LOCATED IN --: | CORNER CODE NUMBER |
|--|----------------|--------------------|
| 1. PUBLIC LAND SURVEY _____ T. 20 N. R. 10 W. | | D-13 |
| 2. PROPERTY CONTROLLING IN SECTION _____ T. _____ N. S. R. _____ E. W. | | |
| 3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. S. R. _____ E. W. | | |
| 4. LOT NO. _____, RECORDED PLAT _____ | | |
| 5. PRIVATE CLAIMS _____ | | |

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 5, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. - Description of original monument and accessories and/or subsequent restoration.~~

B. (continued)

Due N 46'; NE'ly edge Pine Rv. Due E 30'.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-13 Set 1"x66" pipe w/DNR cap in Pine River for S $\frac{1}{4}$ corner Sec. 32, T20N-R10W. Restored corner 4'± north of old irregular E-W fence to W from River and 4'± south of old irregular E-W fn. to E from River in River bottom, & in line with real old N-S fn. remains to N, N from River. Corner restored by this method fits U.S. (G.L.O.) stream tie E to NE'ly edge of River (33' record), fits Geo. Johnson's 1911-1917± survey of SW $\frac{1}{4}$ of Sec. 32 (notes on file with Clint Cole-Lake Co. Surveyor) & fits Frank McClung (1940±) tie of 200'± E to E edge of River in loop. Corner set in 3'± of water, cap is 1.0' below water surface. Put pile of stones around mon. SW'ly edge Pine Rv. Due S 20'; SW'ly edge Pine Rv. Due W 12'; NE'ly edge Pine Rv.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| D-13 | | |
|--|--------|-------------------------------------|
| Set 1"x66" pipe w/DNR cap in Pine River | | Set cedar post w/loc. tag Due W 33' |
| 10" Cedar S25°W | 51.5 | |
| 13" Tamarack S70°W | 60.4 | |
| 3" Cedar Due W | 21.6 | |
| N $\frac{1}{4}$ S5T19N-R10W N89°03'E | 30.81 | |
| Set 5/8"x40" rerod & cedar post w/loc. tag | | |
| N00°59'E | 100.00 | |
| Set 5/8"x35" rerod & cedar post w/loc. tag | | |
| S89°38'W | 200.00 | |

SIGNED BY Carl F. Roser

DATE 7-9-80

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____

DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____

DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

BURDELL TOWNSHIP
OSCEOLA COUNTY