LAND CORNER RECORDATION CERTIFICATE

!	Filing Requiren	nent of Act 74, Mich.	PA 1970	
For Corners In: Osceola Co. (County)	Located In C	Corner Code #		
1. Public Land Survey	TR			
Property Controlling in Section	S 2 T 20N R 10W S T R	9		
Miscellaneous Property in Section	S T R S T R		Register of Deeds Stamp	& File Number
4. Lot No:	Recorded Plat:	<u>.</u>	ABCDEFGHI	J K L M
5. Private Claims:			1 2 - 6 - 5 - 4 3	21
requirements of PA 74, Mic and 2 above were in confor the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	field survey on Feb. 2, 2004 do hereby chigan PA of 1970, the corner points me rmance with regulations and rules therefivey instructions of the United States Dinagement or by a decree of a Court of Latines 3, 4 and 5 above were in conformate Land Surveyors or by a Decree of monumented, recovered, found as expressions.	entioned in lines 1 fore as required in Department of the law and/or that the lince with the rules la Court of Law;	3 4	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			10 -30 - 29 - 28 - 27 -	25
be recorded on this ce	rtmoate.		11 12 31 32 33 34	25 36
			12 31 32 33 34	35 36
A. Description of original monument and accessories and/or subsequent restoration:				
9 - CE 1/16 - None				
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:				
9 – CE 1/16, Sec. 2 – Set 2" aluminum cap on 5/8" x 34" rebar per standard BLM procedure				
		,		
C. Description of monum	nent for corner and accessories estab	blished to perpetuate lo	ocating the position of the corner	:
Set blue carsonite po N24°W 23.42' to set N22°E 4.38' to set N N82°E 10.64' to set I	m cap on 5/8" x 34" rebar ost w/ loc. tag 1' North N & T in W. side 7" R. Maple & T in W. side 12" Hemlock N & T in S. side 8" Cedar I & T in E. side 12" R. Maple		★ Me PROF SU	AIG W. EVEAN ESSIONAL RVEYOR NO. 39088
Signed by:	icerse No.: 39088	Date:	5/20/2004	ESSIOT