SURVEY & REMONUMENTATION

DEC 0 6 1993

	COMMI		RNER RECORDATION CER						
Fo	r corners in	r imig rieq	different of Act 1-1, mion.	T.M. 1010					
	Osceola	Located In:	Corner Code ##						
_	(County)	20N 8W	L-13	APPROVED LAND CORNER P.A. 345 OF 1990 Osceola County					
	Public Land Survey	T R T R		Medical 12 Nov	19	3 3	4		
2.		S T R							
		S T R							
3.		S R		Register o	f Deeds	Stamp	& File	Numb	er
	Property in Sec.	S T R	_						
	Lat Ma	and Disk		•					
					BCD	E F	G H	l J K	LM
Ð.	Private Claims			2	5	⊥ .↓_	↓ 3 _	_2_	
				3			ЬĹ	I. I.	
		_							
	Matthew McClung	g Nin a field survey on	November 5	93 1	í Ti	1 1	T		
−l, do	hereby certify that under requir	irements of P.A. 74 Michigan	P.A. of 1970, the corner points me	ntioned					
			s and rules therefore as required		8	16-	15-	14	13-1
			epartment of the Interior, Bureau		- - -	1	+	₩-	$\vdash \vdash \vdash$
			orner points mentioned in lines 3,		9 20	21-	22	23	24
			ard of Land Surveyors or by a Dec re-monumented, recovered, fo		\Box			ļ	$\sqcup \sqcup$
	oressed below:	established, monumented,	Te-monumented, recovered, 10	103	029		27_	26	25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded									
IVC	on this certificate.	ners, an in the same town	ii and range, may be recorde	123				1	26
	on this certificate.			13	132	33	1 1	35-	
A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by government surveyor John Hodgson, 24 Sept 1837 and was a wooden stake. The corner was set 40 chains west of the Southeast Corner of Section 36. Witnesses: Cedar 7" N12E 30 lks. and Sugar 7" N64W 14 lks.									
В.									
	axle shaft was	found at the S	solid tile at this E edge of the til north edge of til	le. set Osc	eola '	Coun	ty		ເຮ

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - L-13. 3" clay tiles complimented with axle shaft and Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 30" in length.

 10" W. Pine S70W 40.1 feet.

 - 8" Maple East 27.0 feet

 - 5" Maple S25E 14.2 feet 7" Maple N30W 51.35 feet.

MICHIGA McCLUNG LAND SURVEYOR NO November 5, FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

Date 13037 Surveyor's Michigan License No. .

OSCEOLA COUNTY REGISTER OF DEEDS

93 DEC -1 AM 9: 44

Maney Crawford

thereby making the corner 4 feet deep. Sometimes a solid tile, with a cross in the top was used, and sometimes 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the county records. Witnesses: OBT Cedar 7" N12E 30 lks.

This corner was used, but was not recorded or witnessed, in the Highland Twp. book about 1930.

I used the corner again in 1973 in a survey for Highland Heights Subdivision, see PA 74 recording

I again used the corner 12 Nov. 1987 survey for Raymond Rocker, for which I was not paid, and the survey was not recorded, see copy.

I again used the corner in a survey dated 18 dec. 1988 and gave no witnesses.