

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Oscoda

(County)

Located In:

Corner Code #

1. Public Land Survey

T 26N R 2E

B - 3

2. Property Controlling
in Section

S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Liber 4 pg. 69

STATE OF MICHIGAN
OSCODA COUNTY
FILED

2 AUG 95 9:37 A.M.

PATSY J. PETERS

Register of Deeds

I, Marvin E. Myers, in a field survey on June, 19 93
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO-W. Coon July 1839

Mon-Post

WIT: No trees nearby

Fargo Engineering 1908-1909

Mon-Set Mon

WIT: 4" Spruce N30°W 40 lks.

4" Spruce N72 3/4°W 107 1/2 lks.

G.F. DeLamater Feb. 24, 1920

Mon-Unknown

WIT: 4" S.Pine N30°W 43 lks.

4" S.Pine N73°W 167 1/2 lks.

GLO G. Veal Oc. 1935

Mon-Set proportionate Dist.

Conc. Mon. with Brass Tag

WIT: 12" J.Pine N09 3/4°E 45 lks.

8" J.Pine S46 1/2°W 86 lks.

G.D. Henning May 7, 1945

Mon-US GLO Mon.

WIT: None given

Consumers Power Co. G.B. Oct. 1979

Mon-Fd. 3/4" pipe in N. track of drive

WIT: 12" J.Pine SSW 25.41'

14" Db1. J.Pine SSE 56.73'

Fd. post South 33.00'

LCRC L. Beauregard April 1979

L. pg.221

Mon-Fd. 1/2" pipe in N. track trail road

WIT: 8" J.Pine S30°W 25.39'

Fd. 10" J.Pine S35°E 56.71'

Fd. 10" J.Pine S45°W 58.20'

L.3, pg.423 E.J. McCombs May 10, 1984

Mon-Fd. 1/2" Iron in N. track of drive

WIT: 12" J.Pine SSW 25.41'

14" Db1. J.Pine SSE 56.73'

Post South 33.00'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" p. pipe in North track trail road

Found USFS location marker post S09°W 34.10' (33.91' to face)

Found Veal US GLO N12°E 26.42'

Accepted 1/2" pipe as the best available evidence of the original corner and that the recommendation of the
contractor be accepted.

APPROVED

County Remonumentation
Peer Review Group

NCC/31 AUG 95
JULY

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon.-Set 5/8" x 30" Bar with Oscoda County Cap

WIT: Set nail in W. face 12" J.Pine S56°W 58.35'

Fd. PK nail SW. face 11" J.Pine S37°E 56.72'

Set nail in W. face 8" J.Pine N15°W 27.23'

Set nail in W. side USFS location post S09°W 34.10'



Signed by

Marvin E. Myers

Date

July 28, 1995

Surveyor's Michigan License No. 31600