

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Oscoda
(County)

Located In:

Corner Code #

- | | | | | | |
|---|---|-----|---|----|-------|
| 1. Public Land Survey | T | 26N | R | 2E | B - 5 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling
in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous
Property in Section | S | | T | R | |
| | S | | T | R | |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Marvin E. Myers, in a field survey on May 19, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO-W. Coon July 1839
Mon-Post
WIT: 6" Spruce S17°W 91 lks.
4" Spruce N19°E 71 lks.

C.O. Seeley Sept. 23, 1914
Mon-Previously set
WIT: None given

GLO-G. Veal Oct. 1935
Mon-Set Conc. Mon. with
Brass Tablet
WIT: None taken, corner is in a
field.

L.1, pg.78 R. Griffin Apr. 30, 1964
Mon-10" Dock Spike set by intersecting
witnesses
WIT: J.Pine N57°E 108.15'
J.Pine S05°W 68.40'
J.Pine N20°W 126.40'
5"x7' Cedar post North 33.00'
"X" cut in top (N. end) of a
C.M.P. N69°E 58.56'
"X" cut in the (S. end) of a
C.M.P. S64°E 59.70'

N. Caldwell Apr. 1969
Mon-Unknown
WIT: None given
L.4, pg.489 N. Caldwell July 6, 1990
Mon-Placed 5/8" Bar & Cap #12018
over US GLO Mon.
WIT: 9" R.Pine N30°W 40.95'
8" R.Pine N32°E 38.68'
10" J.Pine S06°W 68.65'
7" J.Pine S37°W 61.05'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" I.D. pipe under 10" Dock spike with RLS cap 12018 verified position by measurement
to accessories of record replaced monument with standard monument over USGLO monument.

APPROVED

County Remonumentation
Peer Review Group

NCC/31 #06 95
JULY

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon-5/8" Bar & Oscoda County Cap in pav't box
WIT: 10" J.Pine S06°W 68.65'
7" J.Pine S37°W 61.05'
8" R.Pine N32°E 38.68'
9" R.Pine N30°W 40.95'
USFS L.4, pg.489
Lat 44°39' 0.73935
Long 84°14'29" .85956



Signed by Marvin E. Myers

Date July 28, 1995

Surveyor's Michigan License No. 31600

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983