

SURVEY &
REMONUMENTATION

OCT 08 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 4 Pg. 193

For corners in

OSCODA

(County)

Located In:

MENTOR TWP.

Corner Code #

1. Public Land Survey

T26N R3E

D-1

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

STATE OF MICHIGAN
OSCODA COUNTY
FILED

3 OCT 97 12:05 P.M.

PATSY J. PETERS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, FREDERICK J. KING, in a field survey on July 3, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

D-1 - NORTH 1/4 CORNER OF SECTION 5

NOT SET ON ORIGINAL GOVERNMENT SURVEY

Sept 1930 - GLO ReSurvey by G.R. Veal - Set 2"x36" Iron Pipe with Brass Cap by Prop Dist

On File @ Reg of Deeds - Pg 27

S16°E - 43 lks (28.28') - 8" J Pine

Cor D-13 (27-3) is 16.83' West

S59½°W - 77 lks (50.82') - 4" J Pine

Jan 1971 - Act 132 by N.C. Caldwell, PS #12018 - No Cor Desc - No Wit

On File @ Huron Nat Forest Service Shows Cor D-13 (27-3) 16.85' West

Jan 1971 - Act 74 by N.C. Caldwell, PS #12018 - Found GLO Pipe & Cap - WEST - 16.85' - Cor D-13 (27-3)
No Other Witnesses Marked

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-1 - NORTH 1/4 CORNER OF SECTION 5

FOUND GLO PIPE & BRASS CAP with USFS POST ALONGSIDE

WEST - 16.79' (M) - GLO Conc Mon & Brass Cap @ Cor D-13 (27-3)

APPROVED

County Remonumentation
Peer Review Group

*NCC
30 SEPT 97*

This Corner Approved by County Peer Review on July 11, 1997, as a careful and faithful establishment of the position of the Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-1 - NORTH 1/4 CORNER OF SECTION 5

GLO PIPE & BRASS CAP with USFS Red Top Post Alongside

N60°E - 15.72' - Set S&T on N side of 10" R. Pine

S05°E - 20.91' - Set S&T on E side of 8" R. Pine

WEST - 37.39' - Set S&T on N side of 3" R. Pine

N40°W - 19.76' - Set S&T on E side of 18" R. Pine

WEST - 16.79' (R-16.83' G. Veal & 16.85' N. Caldwell) GLO MON & CAP @ Cor D-13 (27-3)

Signed by

Frederick J. King

Date Sept. 25, 1997

Surveyor's Michigan License No. 25852