

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

OSCODA

(County)

Located In

Corner Code #

1. Public Land Survey

T 27N R 1E J-11

T R

2. Property Controlling in Section

S 35 T 27N R 1E 5

S T R

3. Miscellaneous Property in Section

S T R

S T R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 11, 2001 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

J-11 G.L.O. William R. Coon Dec. 1839

Set quarter section post

Wit: Spruce Pine 10 S17°E 11 Links

Spruce Pine 6 N17°W 15 Links

5- This corner position was not established during the original government survey.

L. 1, page 264, Kenneth Ostling RLS #10068

Set DNR monument by proportionate measurement in Feb. of 1981

Wit: 8" R. Oak N23°W 24.6'

12" B. Oak S89°E 11.6'



B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

J-11 Found DNR monument.

5- Established the Southwest corner of the Northwest quarter of the Northeast quarter of section 35 per B.L.M. instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-11 Found DNR monument

Wit: 14" Oak S79°E 11.69'

7" & 10" Twin Oak N50°W 27.81'

4" White Pine North 33.97'

5" Maple S42°W 19.98'

Carsonite Post North 1'

Smooth wire South and West

5- Set 5/8" X 32" Rerod with P.S. cap #33981

Wit: 6" Maple S38°W 34.53'

8" Oak S19°E 20.72'

18" Twin Oak N26°W 30.39'

18" Oak N26°E 26.51'

Carsonite Post North 1±

Smooth wire North and East

Signed by:

Carl T. Kiiskila

Date:

6-14-01

Surveyor's Michigan License No.:

33981