## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_28\_NR\_1\_W-

			Grawford Otsego COUNTY
DESCRIPTION	OF	CORNER	Section-Corner common to-Sections-1,2,35,36
DESCRIPTION	OF	CORNER	MONUMENT_1% Pipe with 4%-Brass cap
WIT TNESSES	то	CORNER	14" B. Oak - 8.60 F - 21 Links
			_ 24F_Red_PineN_10 F = 14F Links
•			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by double preportionate measurement, by Forestry Division survey crew, while making a partial resurvey of this Brea. There is a  $3/4^{\circ}$  Pipe 1% Links South of this corner. It is erreneous, I believe.

Corner was placed and witnessed September 4, 1952.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 2/20/53 \_