

OTSEGO COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
South Charlton Township

For corners in

Otsego
(County)

Located In:

Corner Code #

1. Public Land Survey

T 29N R 1W

F-7

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Carl T. Kiiskila, in a field survey on September 6, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-7 1856 GLO H. Mellen set quarter section post

Wit: Sp. Pine 7" S45°E 40 links

Sp. Pine 6" N48°E 65 links

County Surveyor's Book 2, Page 560, 1933 G. F. DeLaMater placed a 1 1/2" gas pipe midway in line.

Wit: B. Oak 10" N64 1/4°E 64.6'

B. Oak 8" S3 1/2°E 90.8'

1989 Mitchell and Associates found a 1 1/2" gas pipe midway and approximately 4' off line fitting G. F. DeLaMater's 8" B. Oak witness

LCRC Liber 5, Page 118, (2004) Ronald Brand PS #43046 found 1 1/2" gas pipe approximately 4' off line between section corners for the South 1/4 corner of section 16.

Wit: Oak 14" S2°W 90.91'

Oak 8" N34°E 37.70'

J. Pine 8" N74°E 19.35'

J. Pine 10" N86°W 26.34'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-7 Found a 1 1/4" pipe fitting G. F. DeLaMater's and Ronald Brand's Witnesses approximately midway between section corners and 0.14' North of line. Ronald Brand's calculated position for this corner was incorrect due to an angular error in his calculations.

Oak 14" S2°W 90.75'

Oak 7" N40°E 37.68'

J. Pine 10" N79°E 19.36'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-7 Drove a 5/8" x 34" rerod with Otsego County Cap in found 1 3/4" pipe accepted as careful and faithful re-establishment of the corner position.

Wit: Found nail 12" J. Pine N78°E 19.36'

Set nail & tag 6" J. Pine N30°W 28.44'

Set nail & tag 16" Oak S02°W 90.75'

Set nail & tag 6" J. Pine S72°W 37.33'

Found nail 7" Oak N40°E 37.68'

Centerline trail road South 17'



Signed by

Carl T. Kiiskila

Date

10 / 9 / 07

Surveyor's Michigan License No. 33981