

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Otsego Located In Corner Code #
(County)

1. Public Land Survey T R
T R
2. Property Controlling in Section S 23 T 30N R 4W 11
S 23 T 30N R 4W 12
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on April 20, 1998 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

11- Kenneth J. Ostling RLS# 10068 established this corner while doing a survey for the Department of Conservation in 1961.

12- Kenneth J. Ostling RLS# 10068 established this corner while doing a survey for the Department of Conservation in 1961.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

11- Found 1" pipe as set by Kenneth J. Ostling during a 1961 survey.

12- Found 1" pipe as set by Kenneth J. Ostling during a 1961 survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

11- 1" iron pipe

Wit: *5" White pine S60°W 12.56'
5" White pine S72°E 13.57'
*3" Spruce S29°E 3.85'
4" Maple N08°E 27.48'
Carsonite post North 1'

12- 1" Iron pipe

Wit: 8" White pine S34°E 17.84'
5" White pine N24°E 29.86'
*3" White pine N53°E 3.89'
4" Maple clump N62°W 26.77'
28" Pine stump(center) N38°W 6.8'
Carsonite post North 1'

* Blazed witnessed by others.

*Blazed witnessed by others

Signed by: Carl T Kiiskila
Surveyor's Michigan License No.: 33981

Date: 1-20-00

