

SOTSEGO COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Otsego
(County)

Located In Charlton
Twp. North

Corner Code #

1. Public Land Survey	T	31N	R	1W	L-3
	T		R		
2. Property Controlling in Section	S	T		R	
	S	T		R	
3. Miscellaneous Property in Section	S	T		R	
	S	T		R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on June 19, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

L-3 ¼ Corner common to Sections 1&12 T31N, R01W

1850 – GLO – Austin Burt- Set ¼ sec. post
W. Pine 12 N47W 4
W. Pine 14 S39E 11

1940 – Co. Surveyor Bk. 2, Pg. 378
G.F. DeLaMater P.S. #2674
found both Gov't B's & P.
½"x30" bar in corner.
W. Pine stump 12 East 13.5'
W. Pine stump 20 S19°W 96.1'
W. Pine stump 14 S 19°W 90.3'
W. Pine stump 20 S68°W 73.1'

1981- Liber 2, page 213 Danny M. Bongiovanni
P.S. #24586 found a ½" iron bar
4" R. Pine S10°E 41.87'
8" R. Pine S62°E 35.92'
8" Poplar N40°W 20.7'
Pine stump N40°W 2.98'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

L-3 ¼ Corner common to Sections 1&12 T31N, R01W
Found a ½" bar fitting G.F. DeLaMater's survey in
section 1. Drove 1" x 3' pipe with DNR
aluminum cap over found ½" bar.
Pine stump remains N40°W 3'

Accepted as a careful and faithful perpetuation
of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-3 ¼ Corner common to Sections 1&12 T31N, R01W
Stamped 4" diameter DNR aluminum cap on 1" x 3"
galvanized pipe.

Wit N10°E 25.78' to set N&T on W side 8" W. Pine
S88°E 63.30' to set N&T on S side 14" R. Pine
S16°E 78.78' to set N&T on NE side 14" R. Pine
S44°W 37.44' to set N&T on NW side 15" R. Pine
S62°E 75.00' to set N&T on N side 9" R. Pine
Pine stump remains N40°W 3'
Set blue post 1' North



Signed by:

Carl T Kiiskila

Date:

10-14-13

Surveyor's Michigan License No.:

33981