

FEB 24 2000

SECTION

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

99 OCT 27 PM 1:49

Ray S. Lampen
REGISTER OF DEEDS
OTTAWA COUNTY, MI

For corners in

Ottawa
(County)

Located In:

Corner Code #

1. Public Land Survey T5N R15W J-3
T R
T R
T R
North 1/4 corner
Section 11
Holland Twp.
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Steve Lampen, in a field survey on September 15, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

J-3 County Records show J-3 to K-3 = 2642.3, meas. 2645.55
GLO - Brookfield - 1832
1/4 section post
Beech 10 N 36 E 17
Beech 12 S 36 W 15
L.C.R.C., L6, P66 - Brintnall - 1990
Found 1/2" iron in line with occupation N & S
N 35.11 16-D nail W side 24" Osage Orange
S 3.5 centerline of bituminous Quincy Street
SSE 61.06 nail and tag W side 24" Catalpa
SE 101.91 NW corner house

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-3 Found 1/2" iron in monument box.
N 35.11 16-D nail W side 24" Osage Orange
S 3.5 centerline of bituminous Quincy Street
SSE 61.06 nail and tag W side 24" Catalpa
SE 101.91 NW corner house

Old fence to North and South East 4.5'

County Records show J-3 to be on fence line, J-3 to K-3 = 2642.3, meas. 2645.55

Replaced 1/2" iron with an Ottawa County Remonumentation iron and cap and accepted it as the best position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-3 Ottawa County Remonumentation iron and cap in monument box

Azimuth = Michigan State Plane grid direction

Survey tag No. #14091 in W side 24" Catalpa	171° 48'	61.05
Survey tag No. #14091 in N side Power pole	104° 50'	151.23
NW corner house, brick	145° 37'	101.80
NE corner house, brick	124° 43'	159.99
Hydrant top centerline	58° 55'	54.06
Centerline E and W asphalt road pavement	180°	3.5



Signed by *Steven Lampen*

Date OCTOBER 25, 1999

Surveyor's Michigan License No. 37279