

SURVEY &
REMONUMENTATION

APR 24 1995

OTTAWA COUNTY REMONUMENTATION

RECORDED

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

94 DEC 14 AM 9:39

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in OTTAWA

(County)

Located In:

Corner Code #

1. Public Land Survey

T 6N R 13W

G-12 (E 1/4 cor
of Sec 33)
Georgetown Twp.

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

I, Randal J. Vugteveen, in a field survey on November 23, 19 94

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
G-12 common corner to Sections 33 & 34

1831 - Lyon & Sibley

Set H.M.P.

B. Ash 10" S33E 37 Links

Do 9" N3W 21 Links

Liber 2, Page 703

Nail in side 36" stump N 214.4'

Post is 8' NW of intersection of ditches

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
G-12 Found fence post 2' NW of intersection of ditches E & S, fnd guards and "L" iron & nail 0.1' over bottom of fence post and accepted as a careful and faithful perpetuation of the position of the original corner
Post is 8' NW of intersection of ditches

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
G-12 Removed fence post, set 1 1/2" X 10' galvanized pipe with Ottawa County Remon Cap

AZ = Michigan State Grid Direction

Set Ottawa County Remon Tag & Nail in W side 10" Cottonwood AZ. 0 deg 975.97'

Set Ottawa County Remon Tag & Nail in N side 16" Elm AZ. 90 deg 1102.79'

Set Ottawa County Remon Tag & Nail in W side of 24" Twin Wild Cherry AZ. 176 deg 825.16'

Centerline 22nd Avenue AZ. 90 deg 1338.44'

P.A. 345 OTTAWA COUNTY
PEER APPROVED 12/12/94

Randal J. Vugteveen

Signed by

Date

Dec 9, 1994

Surveyor's Michigan License No.

28429

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

REMON LIBER 2 PAGE 5

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

