SURVEY & REMONUMENTATION

APR 2 4 1995

5. Private Claims _

expressed below:

COMMISSION

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 RECORDED

94 DEC 15 AM 11: 49

Dhydlie Buthan

For corners in				Scholle Karleman
	Ottawa (County)	Located In: Robinson Twp.	Comer Code ##	REGISTER OF DEEDS OTTAWA COUNTY, MI
1.	Public Land Survey	T <u>7N</u> R <u>15W</u> T R T R T R	A-6 W 1/4 Corner Section 18	
	Property Controlling in Section	S T R S T R		
	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

I, Carl P. Englert, in a field survey on October 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

_ , Recorded Plat ____

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11

Description of original monument and accessories and/or subsequent restoration: A-6 West 1/4 corner Section 18

Found Iron Pipe from Co. Surveyor Ties

LCRC Liber 4,	Page 315 (4/1	2/82)
Set Cast Iron	Monument	
16" Ash	WEST	36.60
10" Maple	SW	57.66
19" Maple	EAST	47.53
Grand Haven Co	orner SOUTH	41.61

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-6 West 1/4 corner Section 18

Found 3" Harrison CIM Found 16" Ash WEST 36.60 Found 30" Maple EAST 47.53 Found G.H. Corner SOUTH 41.59

P.A. 345 OTTAWA COUNTY

PEER APPROVED 12/12/94

Ascalon D. Mederson

Accepted as a careful and faithful perpetuation of the accepted position of the West 1/4 corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

A-6 West 1/4 corner Section 18

3" Harrison CIM with Broken top in Mon. Box 3'+/- W. of Road & 57.07' O.C. Remon. Tag & Nail in S.E. side 7" Maple S54°W N83oMO.C. Remon. Tag & Nail in S. side 22" Ash 36.98' N450W 52.071 O.C. Remon. Tag & Nail in N.E. side 28" Maple **5880E** 48.02' O.C. Remon. Tag & Nail in N. side 30" Maple O.C. Remon. Tag & Nail in N.E. side 12" Maple Corner T7N, R16W \$54°E 41.16' SOUTH 41.59' Corner is 0.10' West of a line between E1/4 Cor. 13-7-16 and NE Cor. Sec. 13-7-16

Surveyor's Michigan License No. __

____ Date _/Z/11 /94

E OF MICH ENGLERT JR. **PROFESSIONAL** SIONAL

MANAGE RAID

SEMITED STATES FORM APPROVED BY MICHIGAN STATE BOARD OF LAN REVISED JAN., 1983