

SURVEY &
REMONUMENTATION

NOV 10 1993

COMMISSION

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

1993 SEP 29 PM 3:14

For corners in

Ottawa (County) Located In: Corner Code ##

1. Public Land Survey	T <u>8N</u> R <u>13W</u>	<u>G-7 (SW, 15)</u>
	T _____ R _____	<u>Wright Twp.</u>
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Donald W. Schiele, in a field survey on Sept. 18, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
G-7 corner common to Sections 15, 16, 21 and 22 Wright Twp.

L.C.R.C. recorded in Liber 1, Page 811

Monument Box

No Witnesses

L.C.R.C. recorded in Liber 5, Page 279

C.I.M.

PP

SE. 82.95

Top & Center of Telephone Ped.

SW. 42.23

Face - Gas Pipeline

Sign

NW. 44.15

Top & Center of Gas

Pipeline Sign Post

NE. 70.80

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-7

Found C.I.M. Inscribed "Section Corner" in Monument Box and accepted as a careful and faithful perpetuation of the position of the original corner.

Top and Center of Gas Pipeline Sign Post

NE. 70.40'

Top and Center of 4" square post for Gas Line Valve

NE. 70.80'

Found PK nail in West side of Power Pole

SE. 82.99'

Found PK nail in NE side of Power Pole

SE. 83.33'

Found nail in NW side of Power Pole

SE. 82.77'

Top and Center of Telephone Pedestal

SW. 42.9'±

Face of Gas Pipeline Sign Post

NW. 44.13'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-7

Cemented 2" dia. Aluminum Ottawa Co. Re-mon. Marker #21272 with 4" long Steel Bar in Monument Box over C.I.M.

Set nail and Ottawa Co. re-mon. tag in NW side of Power Pole

N24°E 165.99'

Set nail and Ottawa Co. re-mon. tag in top and center of 4" square post for Gas Line Valve

N66°E 70.80'

Set nail and Ottawa Co. re-mon. tag in NE side Power Pole

S54°E 83.30'

Face of Gas Pipeline Sign Post

N49°W 44.13'

On CL North, South, East and West asphalt roads

Signed by

Donald W. Schiele

Date

SEPT. 20, 1993

Surveyor's Michigan License No.

23517

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 22, 1985

REMON LIBER 1 PAGE 16

