

DEC 01 1993

COMMISSION

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

93 NOV 11 AM 11:54

Donald W. Schiele
REGISTER OF DEEDS
OTTAWA COUNTY, MI

For corners in

Ottawa (County) Located In: Corner Code ##

1. Public Land Survey T 8N R 13W I-7 (SE, 15)
T _____ R _____ Wright Twp.
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Donald W. Schiele, in a field survey on November 2, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
I-7 corner common to Sections 14, 15, 22 and 23 Wright Twp.
T.C.R.C. recorded in Liber 2, Page 663, 10-21-74.

Iron in Monument Box
NE Corner Hse Fndn. SW. 113.59'
Spike in 22" Maple NE. 41.74'
P.K. Nail in P. Pole NW. 49.35'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-7 Found 1" Steel Bar in Monument Box and accepted as a careful and faithful perpetuation of the position of the original corner.
Spike in SE side 30" Maple NE 41.65'
NE Corner House Fndn. SW 113.59'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-7 Moved Monument Box to Center on Corner and set 3/4" X 24" solid bar with Ottawa County Remon Cap in place of 1" Steel Bar.
Set Ottawa County Remon Tag & nail in SE side of 30" Maple N52°E 41.67'
Set Ottawa County Remon Tag & nail in NE side of Power Pole S61°E 55.25'
NE Corner House Fndn. S50°W 113.59'
Set Ottawa County Remon Tag & nail in SW side of Power Pole N49°W 46.36'
On Centerline asphalt road South
Centerline asphalt road West, 1' South
Centerline gravel road North, 3' East
Centerline gravel road East, 5' South

Signed by Donald W. Schiele Date Nov. 8, 1993
Surveyor's Michigan License No. 23517

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 13, 1975
REVISED JAN., 1983

