

OCT 3 0 1997

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

ONTONAGON
(County)

Located In:

Corner Code #

JUDITH D. ROEHM
Ontonagon County
LC 4/275 JUI06/12/97
09:47Fee: 9.00
Page 1 of 1

1. Public Land Survey

T48N R39W

J-3

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Quarter Section Corner common to 2 & 11, T48N R39W.

I, Earl W. Applekamp, in a field survey on May 29, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Artemas Curtis, U.S. Deputy Surveyor, September 1851. Set Wood Post.

ORIGINAL BEARING TREES:

12" Aspen N45°W 7.92 feet
12" W. Pine S70°E 13.20 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. The corner position is at the intersection of roads running East, West and North. An iron pin was found at this position. An old (60 years) fence runs South. The position of the iron pin is in conformance with the original field notes. I accepted the iron pin and monumented it as shown in "C".

Research on file with the Ontonagon County Remonumentation Program Representative.

PEER GROUP APPROVED

Earl W. Applekamp
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I placed a 3" stamped cap on the 1/2" iron pin 6" below the top of gravel. I established a reference monument, a 2 1/2"x30" aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N, R39W, 1/4, R.M., S2, S11, 1997, P.S. 17610. I established three other bearing trees.

REF. MON. S11°E 34.22 feet - 9" Spruce N25°E 62.13 feet
6" Cedar S38°W 43.19 feet - 17" Oak N77°E 90.65 feet



Signed by

Earl W. Applekamp

Date May 31, 1997

Surveyor's Michigan License No. _____

17610