

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON
(County)

Located in:

Corner Code #

1. Public Land Survey

T48NR 39W

L-3

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

$\frac{1}{4}$ Corner common to Section 1 & 12, T48N R39W.

I, Earl W. Applekamp, in a field survey on July 11, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Artemas Curtis, U.S. Deputy Surveyor, September 1851. Set Wood Post.

ORIGINAL BEARING TREES:

8" Aspen N59°E 4.62 feet
7" Aspen S50°W 18.48 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. A yellow tag was found on a tree set by Champion International on 6-19-92, marked approximate corner 6 feet East. This tree was N64°E, 15 feet from where I ultimately set the corner. I re-established the corner by single proportionate measure and on line with opposite section corners East and West.

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 $\frac{1}{2}$ "x30" aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R39W, $\frac{1}{4}$, S1, S12, 1997, P.S. 17610. I established three bearing trees and a bearing object.

6" Hard Maple N83°W 11.86' - 5" hard Maple N33°E 17.82'
4" Hard Maple N19°W 23.16' - Steel Sign Post, South 0.98'

Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date July 14, 1997

REMONUMENTATION

OCT 3 1997

COMMISSION

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

PEER GROUP APPROVED

Earl W. Applekamp
COUNTY REPRESENTATIVE
7-15-97

