

DEC 16 1996

COMMISSION

JUDITH D. ROEHM  
Ontonagon County  
LC 4/ 92 JEM Fee: 9.00  
07/11/96 08:45  
Page 1 of 1

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON (County)	Located In:	Corner Code #
1. Public Land Survey	T48N R40W	H-7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

1/4 Corner common to Sections 15 & 28, T48N R40W.

I, Earl W. Applekamp, in a field survey on June 13 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wells Burt, U.S. Deputy Surveyor, May 24, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

Fir	10"	N12°W	11 links
W. Birch	8"	S57°E	24 links

PEER GROUP APPROVED  
Earl W. Applekamp  
COUNTY REPRESENTATIVE  
07-08-96

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. At the corner position I found a R.R. spike below the gravel. This position is at the intersection of a "T" gravel road. This position is in conformance with original distances to corners South and East and West. Corner was set at the R.R. spike location. This is the only logical position for the corner.

Research on file with the Ontonagon County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8"x24" rebar with a 3/4" stamped cap, 4" below top of a gravel road. I established one reference monument, a 2 1/2"x30" aluminum pipe with a 3/4" cap stamped to read: County Remonumentation, 1/4, R.M., T48N R40W, 1966, P.S. 17610. I established three other bearing objects.

24" W. Pine	S39°-34'-13"W 58.80'	- 30" W. Pine	N38°-29'-16"E 59.66'
Utility Pole	N43°-08'-18"W 49.08'	- REF. MON.	S53°-07'-02"E 56.88'



Signed by Earl W. Applekamp  
Surveyor's Michigan License No. 17610

Date June 24, 1996