

APR 29 1996

COMMISSION

JUDITH D. ROEHM
Ontonagon County
LC 3/ 301 JEM Fee: 9.00
Page 1 of 1

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
ONTONAGON
(County)

Located In:

Corner Code #

- | | | | | | |
|------------------------------------|---|----|---|----|-----|
| 1. Public Land Survey | T | 48 | R | 41 | E-3 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Section | S | | T | R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Section corner common to Sections 4, 5, 8 & 9,
T48N R41W.

I, Earl W. Applekamp, in a field survey on May 23, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Wills Burt, U.S. Deputy Surveyor,
June 1851. Set post.

Original Bearing Trees:

Tamarack	10"	S65°W	1.21 Chains (79.86')
Spruce	8"	N16°E	1.11 Chains (73.26')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner was found. Corner location was
re-established using an abandoned road running West from the
corner position and a County Road running North and South along
the apparent Section line. Corner is in agreement with original
field note calls. This corner was one of the corners re-monu-
in a block of 6 Sections in which all original corners were
re-established.

Research on file with the County Re-monumentation Representative

PEER GROUP APPROVED

Earl W. Applekamp 8-08-95

C. Description of monument for corner and accessories established to locate the position of the corner:

AT the corner position I set a 3/4"X18" aluminum rod with a
3/4" cap, 6" below top of gravel road, stamped to read: County
Remonumentation, S4, S5, S8, S9, T48N R41W, 1995, P.S. 17610.
I established the following witness trees and objects.

6" Aspen	N18°W	200.34 feet	P. Pole	N51°W	39.65 feet
7" Aspen	S48°W	115.44 feet	Witness corner	West	28.75 feet

Signed by Earl W. Applekamp

Date June 10, 1995

Surveyor's Michigan License No. 17610

