

SURVEY &
REMONUMENTATION

APR 29 1996

COMMISSION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

JUDITH D. ROEHN
Ontonagon County
LC 3/ 330 JEN Fee: 9.00
Page 1 of 1

For corners in

Ontonagon
(County) Located In: Corner Code #

1. Public Land Survey T ~~48N~~ R ~~42W~~ ~~18E~~ ~~18E~~
T ~~48N~~ R ~~42W~~
T ~~48N~~ R ~~42W~~
OTHER T 48N R 42W #010 pm

2. Property Controlling S ~~48N~~ T ~~42W~~ R ~~18E~~
in Section S ~~48N~~ T ~~42W~~ R ~~18E~~

3. Miscellaneous S ~~48N~~ T ~~42W~~ R ~~18E~~
Property in Sec. S ~~48N~~ T ~~42W~~ R ~~18E~~

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____
Meander corner common to Sections 7 and 18, T48N, R42W

I, John R. Garske, in a field survey on September 7, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

- On August 10, 1848, Austin Burt set a cedar post from which an 11" W. birch bears S35°E, 19 links and a 7" W. birch - N32°E, 18 links.
- On May 13, 1978, Earl W. Applekamp, RLS 17610, found a 1" diameter drill steel at corner position.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found the 1" drill steel and accepted it as marking the correct corner position as it lies in harmony with local residences and has been used in several surveys of record.

Record research on file with Register of Deeds.

PEER GROUP APPROVED

Earl W. Applekamp 9-20-95
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 2 1/2" diameter x 30" long aluminum pipe with a 3 1/4" diameter cap stamped: County Remonumentation; T48N; R42W; M.C.; S-7; S-18; 1995; RLS 28410, from which I established the following bearing trees and/or reference objects:

9" cedar - S45°E - 9.39 feet
5" spruce - S12°W - 18.36 feet
6" ash - N66°W - 3.10 feet
6 foot steel rail with sign - N73°E - 2.92 feet

Signed by John R. Garske
Surveyor's Michigan License No. 28410

Date 9-19-95

