

APR 25 1995

**COMMISSION**

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
Ontonagon  
 (County)

Located In: Corner Code #

1. Public Land Survey	T <u>48N</u> R <u>43W</u>	<u>L-3</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Recorded December 7 1994  
 at 4:25 o'clock P. M. in  
 Liber 3 page 240  
*Julia Mark*  
 Register of Deeds

**Register of Deeds Stamp & File Number**

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_  
 One-quarter corner common to Sections 1 and 12, T48N, R43W

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, John R. Garske, in a field survey on October 27, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Survey by Austin Burt on August 16, 1848. Set sugar post from which a 6" sugar bears S20°W, 24 links and a 10" lynn - N25 1/2°E, 32 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence could be found due to logging activity. On October 27, 1994, I found a 2" x 6' iron pipe with hub and tack in it along with a 3/4" square bolt 3 feet long marking the corner position. It has been used in various surveys and accepted by local residents as the one-quarter corner. A 24" basswood with a forest service tag, bears N31°W, 10.8 feet and a 1 1/8" drill steel - S02°-30'W, 44.82 feet.

Corner record research on file.

**ONTONAGON COUNTY**

**PEER APPROVED**

*Earl W Applebaum*  
 Ont. Co. Rep. 11-30-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I updated the corner position to state and county specifications by replacing the 2" iron pipe with a 2 1/2" x 30" aluminum pipe with a 3 1/4" aluminum cap stamped: County Remonumentation; 1/4; S-1; S-12; T48N, R43W; 1994; RLS 28410. I established the following bearing trees and reference object: 8" maple - S76°E, 17.96 feet; 5" maple - N35°E, 22.48 feet; 11" maple - S72°W, 17.68 feet; 6 foot steel rail with sign - due south, 1.10 feet.

Signed by John R Garske  
 Surveyor's Michigan License No. 28410

Date 11/28/94



FORM APPROVED BY MICHIGAN BOARD OF LAND SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN., 1983