

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ontonagon Located In: Corner Code ##
(County)
1. Public Land Survey T 49N R 42W B-5
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

SURVEY &
REMONUMENTATION

APR 07 1998

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

$\frac{1}{4}$ Corner 7 & 18; T.49 N., R.42 W.

I, Richard L. Drahn in a field survey on November 29, 19 97,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt on June 20, 1848. Original B.T.s ---
Y. Birch 13" N.60 E. 29 links (19.14') --- Fir 8" S.25 W. 12 links (7.92')

Corner position re-established on March 17, 1981 by proportionate methods
by Richard L. Drahn (21564). He set a 2" X 30" aluminum pipe with a $3\frac{1}{4}$ "
stamped aluminum cap and the following:

6" Sugar Maple N.66 W. 8.33'
4" Sugar Maple N.08 E. 9.28'
5" Sugar Maple S.88 E. 21.73'
7' Steel sign rail South 2.03'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner recorded in Ontonagon County in Liber 2, Page 64 on June 6, 1982.

Research form on file with Ontonagon County records.

Recovered the corner as described and the bearing trees as follows:

8" Sugar Maple N.71 W. 8.19'
Sugar Maple (dead and down)
9" Sugar Maple S.86 E. 21.71'
7' Steel sign rail South 2.05'

No GLO evidence recovered.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described monument I referenced the following:

16" Cedar S.02 E. 29.63'

PEER GROUP APPROVED

Earl W. Apelkamp
COUNTY CLERK
12-8-97



Signed by Richard L. Drahn Date November 30, 1997

Surveyor's Michigan License No. 21564