12/26/97

Ontonason County 5/ 35 JEM 10:

15:35

Fee: Fase


## LAND CORNER RECORDATION CERTIFICATE

Fo	Filing Requirement of Act 74, Mich. P.A. 1970					
<del></del>	Ontonagon	Located In:	Corner Code ##	SURVEY & REMONUMENTATION		
1.	Public Land Survey	T <u>.49</u> N R <u>4</u> 2W. T R T R	i	APR 0 7 1998		
2.	Property Controlling in Section	T R S T R S T R		SECTION		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number		
		Recorded Plat		A B C D E F G H , I J K L		
5.	Private Claims			2 6 5 4 3 -2 -		

1/4 Corner 5 & 6; T.49 N., R.42 W.

 $I.Richard\ L.\ Drahn\ \ in\ a\ field\ survey\ on\ CDecember\ 3,\ 1997.\ 19\ \underline{\qquad},\ do\ hereby\ certify\ that\ under requirements\ of\ P.A.\ 74,\ Michigan\ P.A.\ of\ 1970,\ the\ corner\ points\ mentioned$ in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE:- Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration: Corner established by William Burt on 6/27/1848. Original B.T.s --- 8" Hemlock S.70 W. 5 links (3.3') --- 6" Sugar East 11 links (7.26') ---

Corner restored by Richard L. Drahn (21564) on 7/12/77 from the remains of the two original B.T.s, line trees and the distance N & S to recovered corners. He set a 2" X 5' iron pipe with a 3" stamped brass cap and the following:

12" Hemlock N.13 W. <u> 31.5'</u> 9". S.86 E. 18.61 Hemlock Sugar Maple Metal sign post 24.51 911 S.11 W. 2.0 7 ' N.84 W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Corner recorded in Ontonagon County in Liber 1, Page 147 on 4/25/79.

Research form on file with Ontonagon County records.

Recovered the monument as described and the B.T.s as follows:

14" N.10 W. 13.55 Hemlock 18.50 11" Hemlock S.86 E. 12" Sugar Maple S.16 W. 24.36' 2.01' Steel sign rail N.82 W.

Hemlock roots and bark still remain from the original Hemlock B.T. and only a depression remains of the original Sugar. .. . . . .

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

New bearing object referenced:

14" Sugar Maple N.52 W. 6.681





Signed by Richard L. Draha Date	December 4, 1997
Surveyor's Michigan License No. 21564	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS.