

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ontonagon Located In: Corner Code #
(County)
1. Public Land Survey T 50N R 38W G-4
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

CONVEY &
REMONUMENTATION

OCT 30 1997

COMMISSION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Joseph C. Domitrovich, in a field survey on September 16, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	13		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

(G-4) 1/4 Corner Common to Sections 9 & 10, T50N, R38W

A. Description of original monument and accessories and/or subsequent restoration:

1847 - Sylvester W. Higgins set post.
8" Balsam S 73° E 12 links
8" Cedar N 70° W 14 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The original corner and accessories have been destroyed by road construction and farming. An East-West gravel road (Savela Road) and a fence to the North are now found at the corner. A single prorated position would fall 3.9 feet West of the fence and 5.5 feet South of the centerline of Savela Road. Therefore, I created a position at the intersection of the centerline and the extension of the fence. I believe this position best represents the original 1/4 corner.

Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" x 24" iron pin with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T.50N, R.38W; S. 9, S. 10; 1/4; 1997; P.S. 37273. I also established a reference monument (R.M.) to the North, a 2" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to indicate that the 1/4 corner is South 21.80 feet.

Witnesses:

Power Pole	S 73° E	119.80'
7" Spruce	S 05° W	34.16'
Power Pole	S 75° W	136.67'
R.M.	N 02° 52' 03" W	21.80'
NE Cor. Section 9	N 00° 30' 32" E	2643.91'
SE Cor. Section 9	S 00° 40' 41" W	2654.87'

PEER GROUP APPROVED

COUNTY REPRESENTATIVE

9-17-97

NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

Signed by Joseph C. Domitrovich

Date 9/16/97

Surveyor's Michigan License No. 37273

