

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

(ONTONAGON COUNTY)		CORNER CODE NUMBER
FOR CORNERS OF --	LOCATED IN --	
1. PUBLIC LAND SURVEY	T. 51 N. R. 37 W. <input checked="" type="checkbox"/>	G-11
2. PROPERTY CONTROLLING IN SECTION 33	T. 51 N. R. 37 W. <input checked="" type="checkbox"/>	2
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W. <input checked="" type="checkbox"/>	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April 30, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner G11: Original monument and accessories not found. Found 1-1/4" I.D. by unknown length iron pipe 18" above ground level. Old fences south - east - west.

Corner 2: Found 1-1/4" I.D. x unknown length iron pipe 28" above ground level. Old fences south and east.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner G11: Restored at 1-1/4" I.D. iron pipe. Information on this corner received from Melvin C. Larsen, Hancock.

Corner 2: Established at pipe. Information on this corner from Melvin C. Larsen, Hancock.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner G11: 1-1/4" I.D. x unknown length iron pipe 18" above ground level.

12" Sugar S33E 14.2 ft., S23, NBT

14" Cedar N20E 40.0 ft., S27, NBT

12" Cedar N37W 29.6 ft., S28, NBT

Corner 2: 1-1/4" I.D. x unknown length iron pipe 28" above ground level.

12" Cedar N49W 46.0 ft., 1/16S, BT

12" Maple N71E 17.4 ft., 1/16S, BT

7" Maple S07W 22.6 ft., 1/16S, BT

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Keith L. Sackett DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

Keith L. Sackett

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 19006

