

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ontonagon

(County)

Located In:

Corner Code #

1. Public Land Survey

T 51N R 38W

J11

T R

T R

T R

T R

2. Property Controlling in Section

S

T R

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Oct 07 1996

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

(J11) Quarter corner common to Sections 26-35. Corner established in 1846 by H. Higgins and S.W. Higgins: "...40.03 Set 1/4 Section Post, Sugar 10 N15W 36, Sugar 12 S20E 20". A monument is shown on SUPERVISOR AHO'S PLAT which appears to be the 1/4 corner, but no specific indication is shown on the face of the plat. This monument is shown in the center of Plank Road 2680' East of Ili. 1966 MSHD records for 1/4 cor. by C.C. Lindgren RLS 14098 show: "Found P.X. nail in Blktop over 4: Sq. Conc Monument in CL of Greenland Rd. 10" Spruce N30W 51.60", 10" Pine N45E 51.25", 4" Sq. Conc. Monument South 33.00". Distance west to I11 is shown as 2680.87', East to K11 as 2609.86', and angle at this corner between the two adjacent section corner is shown as 178 deg. 02 min. 46 sec.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J11) Original post and accessories not recovered. Found a 1/2" iron pin, 1 ft. south of the Centerline of Plank (now Greenland) road. The road is paved with asphalt and the pin was found below. The area was not excavated to a depth which would be sufficient to determine whether or not the pin is set in concrete. Both of the 1966 MSHD witnesses were found in good condition and were found at record bearing and distance. Distances West and East to adjacent section corners were found to be 2679.96' and 2609.25', respectively. The angle in the Section at this pin was found to be 178 deg. 02 min. 47 sec. Accepted the pin as the best available evidence of the position of the original 1/4 corner. Left the pin in place and made two new witnesses as described below. Corner found and re-witnessed by B.Wheeler, Baraga District Office, MDNR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J11) Found 1/2" dia. iron pin
22" Spruce N30W 50.5' Nail/tag
30" W. Pine N48E 50.4' Nail/tag
P. Pole #88-26854 S69E 83.5' to face
P. Pole #90-23329 S68W 60.9' to face
Bearings are magnetic.



Signed by

Stephan J. Szyszkoski

Date

Sept. 17, 1997

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Forest Management Division