

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ontonagon

(County)

Located in:

Corner Code #

1. Public Land Survey

T 51N R 38W

K11

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Oct 07 1996

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 19\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

**A. Description of original monument and accessories and/or subsequent restoration:**

(K11) Section corner common to Sections 25-26-35-36. Corner established in 1846 by H. Higgins and S.W. Higgins: "...80.00 Set post cor. Sec 25,26,35,36, Sugar 12 N45E 35, do 14 S50W 40". MDSH records dated 10-30-68 by C.Koistenen, Survey Chief shows: "Found South-east corner of Sect. 26, being 1" drill rod. 10" Spruce N35W 47.16", 8" Spruce N60E 68.58", 14" Spruce S10E 47.83". Distance west to J11 is shown as 2609.86'. This drill rod was recovered in 1970 by Mi Dept. of Natural Resources surveyors and used as control for reestablishing K12 by single proportionate measurement. MDNR did not record the corner at that time.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(K11) Original post and accessories not recovered. Found a 1" drill rod, in good condition, at record bearing and distance from the 1968 MDSH witnesses, all standing and in good condition. The distance west to J11 was found to be 2609.25'. Accepted the monument as the best available evidence of the position of the original corner. Left the drill rod in place, re-marked the 1968 witnesses, and made one new witness, as described below. From the monument recovered, the centerline of a E-W 2 track is 1 ft. South. Corner recovered and re-witnessed by B. Wheeler, Baraga District Office, MDNR.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(K11) Found 1" drill rod 0.4' below ground surface. Blazed and scribed the following 1968 witness trees:

12" Spruce N76E 68.1' "S25 N8T"


18" Spruce S06E 47.1' "S36 N8T"

18" Spruce N37W 46.8' "S26 N8T"

Distances are to measuring notch cut in lower blaze.

P.Pole #77-1544 S23W 26.9' to face

Bearings are magnetic.



Signed by

*Stephan J. Szyszkoski*

Date

*Sept. 17, 1997*

Surveyor's Michigan License No.

*33986*

For the Michigan Department of Natural Resources - Forest Management Division