## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

## For corners in

Ontonagon (County)	_ Located In:	Corner Code #						
1. Public Land Survey	TR							
2. Property Controlling in Section	S 14 T 51N R 40W S T R S 14 T 51N R 40W	14 (GCDB 600420)						
3. Miscellaneous Property in Sec.	S 14 T 51N R 40W S T R S T R	16 (GCDB 560400)						
4. Lot No. , Rec	orded Plat	Į	Regis	ster of Dee	ds Stamp	& File	Number	
5. Private Claims			1 A B	CDE	FG	HI	J	C L M
			2 - 6-	╌┋╌			_ <u> </u>	!_
ı, Stephan J. Szyszkoski , in	a field survey on 09/6	08/15 do hereby state	3	┼┼┼		┵		$\Box$
that under requirements of P.A. 7	4 7-	┿╌	->-	-10-	-11-	12		
above were in conformance with re	5	┦┈┦┈┤		+	_ _			
instructions of the United States D	6 -1'9-		-16	-15	-14-	13		
a Court of Law and /or that the co	orner points mentioned in lines 3, 4 and 5	above were in conformance with	7	╂	_+	$\overline{+}$		
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			8 -19-	20_	_21	22	_23_	
	eu, Tound as expressed below:	:	9		$\bot\bot$	$\bot$		
NOTE: Not more than 2 corne	and all in Ab		10-30-	29_	-28	27-	_25	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				+	$\bot$	14		
on uns certificate.			12-31-	32	_33	34	_35	
A 50 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		1	سلسادر			1		Ĭ
A. Description of original mo	nument and accessories and/or su	ibsequent restoration:						

(16-Sec. 14) East 1/16 corner between Sections 14 and 23. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 14) South 1/16 corner between Sections 13 and 14. Not previously monumented.

(14-Sec. 14) Established the position for the corner midway and on a straight line between Quarter corner 1310.85' north and Section corner 1310.85' south.

(16-Sec. 14) Established the position for the corner midway and on the Section line between Section corner 1325.95' east and Quarter corner 1325.95' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 6" Sugar North 4.15' mrkd "1/16S BT" 10" twin Basswood N59°E 10.2' do 6" Sugar S35°E 19.55' do 10" Y.Birch S18°W 10.85' do Set sq'd cedar post adjacent.

E= 7821877.653 N= 228065.399

(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 2" Oak S72°E 22.0' mrkd " X X " do 7" Maple N44°W 39.15' "1/16S BT" 4" Maple N13°W 23.1' do Set sgld cedar post addresset

OF MICH

STEPHAN J

SZYSZKOSKI

LAND SURVEYOR No. 33986

AND SU

Set sq'd cedar post adjacent. E= 7821464.876 N= 227676.782

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord.	Ref.=NGS	PID DL6162:	N=	233745.718	m.	E=	7824690	922	π
--------	----------	-------------	----	------------	----	----	---------	-----	---

Signed by Stipher Surveyor's Michigan License No. 33986

Date 10/06/2015

Revised Oct., 1995