JUDITH D. ROEHM Ontonason County C 4/ 279 JJT 06/13/97

Page

Fee: 9.00 1 of 1

## LAND CORNER RECORDATION CERTIFICATE

For corners in	Filin	g Requirem	ent of Act 74	l, Mich. P.A. 19	970						
	Located In:	Corner	Codo#	ŀ							
Ontonagon (County)	Located III.	Come	Code#			- 5	w				
1. Public Land Survey	T <u>51NR</u> TR		E-5		A	EMON	TRACTICAL CO		7.00 Cm /		
	TR_ TR_					OCT	3 0 10	197			
2. Property Controlling in Section	S TR_	S TR S TR				COMMISSION					
3. Miscellaneous Property in Sec.	S TR_ S TR_	S TR					Register of Deeds Stamp & File Number				
d Ladala Bass				<b>L</b>		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		mp at t	TO HOMBO		
4. Lot No , Reco	orded Plat				A B	C D I	E F G	H I	JKL		
			-		2 - 6	<del></del>	4	_3	- 2		
					3			_ _ _			
I, Joseph C. Domitrovich requirements of P.A. 74, Michigan	_, in a field survey on _	June 6	19 <u>97</u> do herei	y state that under	4 7		<u> </u>	_10	-1112		
conformance with regulations ar	gan P.A. or 1970, the come nd rules therefore as require	r points mention	ned in lines 1 an manual of survey	d 2 above were in instructions of the	5		$\rightarrow \rightarrow \rightarrow$				
<ul> <li>United States Department of the</li> </ul>	e Interior, Bureau of Land M	anagement or b	y a decree of a C	ourt of Law and /or	6 -18	-17	16	-15	-1413		
that the corner points mentione Board of Land Surveyors or t					7				+		
recovered, found as expressed to	below:		•	,	819	20	21	_22	-2324-		
NOTE: Not more than 2 co	mers, all in the same towr	n and range, m	nav be recorded		9			$\bot$			
on this certificate.	• • • • • • • • • • • • • • • • • • • •		,		10 30	29	28	_27	-2625		
					11			$\perp \perp$	111		
/E E) Comer of Continue	9 0 40 and 47 T.64	N. 1740\A(			1231	32-	33	_34	-3536-		
(E-5) Corner of Sections	8, 9, 16 and 17, 1 51	N. RAUVV			13						
A. Description of original m	onument and accessorie	es and/or sub	sequent restora	ntion:							
1845 - William A. Burt, D 24" Cedar S 24" Hemlock N	35 <sup>0</sup> W 8 links	5									
B. Description of corner ev	idence found and/or me	thod applied i	n restoring or re	eestablishing corr	ner:						
I found a fence intersection large Cedar stump at GLC					l found t	he scatte	red rem	ains of	а		
I accepted the fence inter					stream c	rossing to	South	and wil	th comer:		
North and West. Corner	falls 12' West of cente	erline of an	old railroad g	rad <del>e</del> .							
Research on file with Cou	inty Remonumentatio	n Represen	tative.								
C. Description of monumen	t for corner and accesso	ries establish	ed to perpetuat	e locating the pos	sition of th	e corner:					
Corner is a 5/8" x 48" iron S. 8, S. 9, S. 16, S. 17; 19		ər aluminum	cap stampe	: COUNTY RE	MONUN	/IENTATI	ON; T.5	1N, R.4	40W;		
Witnesses:	·		PERR	GROUP APPR	OVED			PROPERTY.	MOON		
	104 <sup>0</sup> E	14.38'	2.0	11/10	1.	_	A STATE OF	E UT R	CHICA		
	5 77 <sup>0</sup> E 5 15 <sup>0</sup> W	35,90' 12,97'	COUNT	<u>U apple</u>	Brius	<del></del>	# ST	F 1000	To 2.00		
· · · · · · · · · · · · · · · · · · ·	Vest	1.50'	PATON.		6-	10-97	# D	JOSEI OMITRO			
Steel Sign Post N	lorth		(to face)		-			SURVE			
S 1/4 Corner Sec. 8 S	89 <sup>0</sup> 46' 22" W	2612.46	• • • • •			1	EST .	No.	#		
E 1/4 Corner Sec. 8 N	l 00 <sup>0</sup> 11' 12" W	2628.62					1:/	3727			
NOTE: Bearings are ma	- ( + .	to nail in si	ide of witness	_	s noted.	6/9/91	1	A H C	NEW TOWN		
Signed by Chr. C. N	out he			Date		414147	74				

Signed by AL

Surveyor's Michigan License No.

Date